



DX64WCU

report date: 2024-03-28

General information

Make	MAZDA
Model	3 D SPORT NAV
Colour	Blue
Year of manufacture	2014
Top speed	130 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 1.800 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.6 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-15
Pictures	0
Listing price	View report

source: **autotrader.co.uk**



MOT history

MOT expiry date	2024-06-16
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #8 2023-06-06 09:09

MOT test number 799032211105

Result ✓ Passed

Next expiry date 2024-06-16

Advice Under trays fitted**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement back bushes on both front bottom arms worn/slight movement (5.3.4 (a) (i))

MOT #7 2022-05-31 14:06

MOT test number 970349497578

Result ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Items removed from driver's view prior to test

MOT #6 2021-06-17 14:43

MOT test number 466201607686

Result ✓ Passed



MOT #5	2020-09-15 14:42
MOT test number	437293703703
Result	✓ Passed
Minor	Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #4	2019-09-03 08:44
MOT test number	440175031188
Result	✓ Passed
Advice	Nearside Non obligatory mirror damaged
Advice	Nearside Front Door catches when open due to sill damage
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3	2018-09-18 08:21
MOT test number	900311908443
Result	✓ Passed
Advice	Non obligatory mirror damaged

MOT #2	2017-09-20 13:14
MOT test number	916200015574
Result	✓ Passed

MOT #1	2017-09-19 13:18
MOT test number	910222408723
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit also worn smooth on inner edge, recommend replace (4.1.E.1)
Fail	Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
Advice	Nearside Front Tyre worn close to the legal limit also worn smooth almost to cords on inner edge, recommend replace (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
16 June 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	16 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-09-01
Last registration	2023-06-06
Complete history	See info



Registration #1	2014-09-01	24 mi
Registration #2	2017-09-19	36.842 mi
Registration #3	2017-09-20	36.843 mi
Registration #4	2018-09-18	49.909 mi
Registration #5	2019-09-03	62.432 mi
Registration #6	2020-09-03	75.000 mi
Registration #7	2021-09-03	87.568 mi
Registration #8	2022-09-03	100.136 mi
Registration #9	2023-06-06	112.704 mi
Registration #10	2023-06-06	112.704 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	86%
Pedestrian	65%
Safety systems	81%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1465 mm
Length	4465 mm
Wheel base	2700 mm
Kerb weight	1320 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	SH 30455645