



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS TDI SE
Colour	Red
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	156 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-08-05
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-26
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	24
Total items failed	4

MOT #16	2023-07-19 08:08
MOT test number	618802791895
Result	✓ Passed
Next expiry date	2024-07-26
Advice	Brake disc worn, pitted or scored, but not seriously weakened Rear discs corroded (1.1.14 (a) (ii))
Advice	Anti-roll bar linkage ball joint has slight play Both rear (5.3.4 (a) (i))
Advice	Tyre slightly damaged/cracking or perishing Rear tyres stepping inner edges (5.2.3 (d) (ii))

MOT #15	2022-07-18 10:53
MOT test number	204955617968
Result	✓ Passed

MOT #14	2021-07-27 13:39
MOT test number	739719972215
Result	✓ Passed

**MOT #13** 2020-11-10 09:58**MOT test number** 233031352312**Result** ✓ Passed

- Advice** Centre exhaust sleeve deteriorated
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Inner face (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Inner and outer faces (1.1.14 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened Inner and outer faces (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Inner and outer faces (1.1.14 (a) (ii))

MOT #12 2019-11-06 10:22**MOT test number** 797604128664**Result** ✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Inner disc corroded slightly (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Disc corroded (1.1.14 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened Inner disc corroded slightly (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Disc corroded (1.1.14 (a) (ii))

MOT #11 2018-11-21 15:38**MOT test number** 742379857158**Result** ✓ Passed**MOT #10** 2018-11-17 09:35**MOT test number** 382691735240**Result** ✗ Failed

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Offside Front Suspension arm pin or bush excessively worn Rear console bushes (5.3.4 (a) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn Rear console bushes (5.3.4 (a) (i))

**MOT #9** 2017-11-21 09:02**MOT test number** 244845067154**Result** ✓ Passed**MOT #8** 2017-03-08 12:37**MOT test number** 747364312959**Result** ✓ Passed**Advice** Both rear tyres wearing on inner edges**Advice** Nearside front tyre sidewall damaged**MOT #7** 2016-02-16 11:09**MOT test number** 351266965827**Result** ✓ Passed**Advice** Slight wear on front and rear brake discs**MOT #6** 2015-03-03 13:00**MOT test number** 669762465070**Result** ✓ Passed**Notice** O/s/f tyre wear on inner edge**Notice** Wear and corrosion on rear discs**MOT #5** 2014-02-25 09:03**MOT test number** 148056054036**Result** ✓ Passed**Notice** N/s/f tyre has damage to side wall

**MOT #4** 2013-02-06 12:10**MOT test number** 977557233088**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** N/S/R Tyre nail in center also worn on inner edge**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Emissions to low to record on tester PASS**Notice** O/S/R Tyre worn on inner edge**MOT #3** 2012-02-22 11:28**MOT test number** 705993852042**Result** ✓ Passed**MOT #2** 2011-02-25 11:47**MOT test number** 669146151036**Result** ✓ Passed**MOT #1** 2011-02-18 11:26**MOT test number** 545059941031**Result** ✗ Failed**Notice** N/S/F TYRE 2MM,NEARLY BALD ON INNER & DAMAGE TO SIDEWALL**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
26 July 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	26 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 FE08LLT
Plate since	2019-06-29
Current registration	 FE08LLT
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-01
Last registration	2023-07-19
Complete history	See info



Registration #1	2008-03-01	29 mi
Registration #2	2011-02-18	51.153 mi
Registration #3	2011-02-25	51.356 mi
Registration #4	2012-02-22	58.641 mi
Registration #5	2013-02-06	65.349 mi
Registration #6	2014-02-25	72.447 mi
Registration #7	2015-03-03	79.247 mi
Registration #8	2016-02-16	84.328 mi
Registration #9	2017-03-08	91.010 mi
Registration #10	2018-03-01	95.377 mi
Registration #11	2019-03-01	95.377 mi
Registration #12	2020-03-01	95.377 mi
Registration #13	2021-03-01	95.377 mi
Registration #14	2022-03-01	95.377 mi
Registration #15	2023-03-01	95.377 mi
Registration #16	2024-03-01	95.377 mi
Registration #17	2025-03-01	95.377 mi
Registration #18	2026-03-01	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1715 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKP 293807