



**MI8RGC**


report date: 2024-03-28

General information

Make	JAGUAR
Model	XK CONVERTIBLE
Colour	Silver
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	6.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	294 BHP
Max. torque	410 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	34.9 mpg
Consumption combined	25.0 mpg
CO2 emission	269 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-06-19
Pictures	46
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-28
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	17
Total items failed	9

MOT #18	2024-04-24 09:36
MOT test number	734046494728
Result	✓ Passed
Next expiry date	2025-04-28

MOT #17	2024-04-23 11:42
MOT test number	214493331567
Result	✗ Failed
<div>Pass with rectification</div> Nearside Headlamp aim too high (4.1.2 (a))	
<div>Fail</div> Offside Rear Suspension rod ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	
<div>Fail</div> Nearside Rear Suspension rod ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	

**MOT #16**

2023-04-21 11:12

**MOT test number**

466741196668

**Result**

✓ Passed

- Minor** Offside Rear Inner Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Rear Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Rear Outer Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Rear Outer Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement inner (5.3.4 (a) (i))
- Minor** Nearside Rear Inner Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #15**

2023-04-17 10:47

**MOT test number**

837225555352

**Result**

✗ Failed

- Minor** Nearside Rear Inner Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Rear Inner Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Rear Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Minor** Nearside Rear Outer Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement inner (5.3.4 (a) (i))
- Minor** Offside Rear Outer Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #14** 2022-04-26 10:47**MOT test number** 518474332351**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2021-04-29 11:21**MOT test number** 942132746640**Result** ✓ Passed**MOT #12** 2021-04-28 08:57**MOT test number** 183335951170**Result** ✗ Failed**Fail** Rear Service brake excessively fluctuating (1.2.1 (e))**Fail** Nearside Rear Valve stem seriously damaged (5.2.3 (j))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Front Service brake excessively fluctuating (1.2.1 (e))**Fail** Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #11** 2020-03-24 10:01**MOT test number** 414798390894**Result** ✓ Passed**MOT #10** 2019-03-13 10:43**MOT test number** 977962601797**Result** ✓ Passed



<b>MOT #9</b>	2018-03-20 10:48
<b>MOT test number</b>	937189774201
<b>Result</b>	✓ Passed
<b>MOT #8</b>	2017-02-27 10:07
<b>MOT test number</b>	897495467405
<b>Result</b>	✓ Passed
<b>MOT #7</b>	2016-02-29 11:09
<b>MOT test number</b>	410077282087
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2015-03-20 09:59
<b>MOT test number</b>	345249775008
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2014-03-21 10:26
<b>MOT test number</b>	936780584046
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2013-03-14 11:31
<b>MOT test number</b>	406553173082
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2012-03-22 16:09
<b>MOT test number</b>	355472582016
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2011-03-16 16:57
<b>MOT test number</b>	625055271067
<b>Result</b>	✓ Passed



MOT #1	2010-01-14 11:15
MOT test number	840524510085
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
28 April 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	28 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	M
<b>Single payment (12 months)</b>	£ 695,00,-
<b>Single six month payment</b>	£ 382,25,-
<b>Total payable by 12 monthly instalments</b>	£ 729,75,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-01-24
Last registration	2024-04-24
Complete history	<a href="#">See info</a>



Registration #1	2007-01-24	24 mi
Registration #2	2010-01-14	20.997 mi
Registration #3	2011-03-16	27.273 mi
Registration #4	2012-03-22	30.213 mi
Registration #5	2013-03-14	32.865 mi
Registration #6	2014-03-21	35.186 mi
Registration #7	2015-03-20	36.581 mi
Registration #8	2016-02-29	37.162 mi
Registration #9	2017-02-27	37.712 mi
Registration #10	2018-03-20	38.375 mi
Registration #11	2019-03-20	39.038 mi
Registration #12	2020-03-20	39.701 mi
Registration #13	2021-03-20	40.364 mi
Registration #14	2022-03-20	41.027 mi
Registration #15	2023-03-20	41.690 mi
Registration #16	2024-03-20	42.353 mi
Registration #17	2025-03-20	43.016 mi
Registration #18	2026-03-20	43.679 mi
Registration #19	2027-03-20	44.342 mi
Registration #20	2028-03-20	45.005 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4791 mm
Wheel base	2752 mm
Kerb weight	1635 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	07032609435G