



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI AIRDREAM DSPORT PLUS
Colour	Yellow
Year of manufacture	2013
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-14
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	39
Total items failed	14

MOT #16	2024-03-12 09:31
MOT test number	816275210860
Result	✓ Passed
Next expiry date	2025-03-14
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated clip (6.1.7 (g) (i))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Front Play in steering rack inner joint(s)
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #15**

2024-03-07 11:33

**MOT test number**

914086595739

**Result****✗ Failed**

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated clip (6.1.7 (g) (i))

**MOT #14**

2023-03-06 12:21

**MOT test number**

677445899111

**Result****✓ Passed**

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #13**

2022-03-09 13:02

**MOT test number**

801060135123

**Result****✓ Passed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust mounting defective (6.1.2 (a))

**MOT #12** 2022-03-05 09:03**MOT test number** 313255040968**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Exhaust mounting defective (6.1.2 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2021-02-22 16:24**MOT test number** 603136986525**Result** ✓ Passed**MOT #10** 2020-03-12 15:40**MOT test number** 682612837797**Result** ✓ Passed**MOT #9** 2020-03-12 12:11**MOT test number** 614310548044**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #8** 2019-03-15 17:10**MOT test number** 175920560834**Result** ✓ Passed

**MOT #7** 2019-03-15 17:10**MOT test number** 664840134255**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #6** 2018-04-19 18:18**MOT test number** 312740702387**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2017-03-22 15:19**MOT test number** 382618779210**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2017-03-22 13:15**MOT test number** 513546395001**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Rear Exhaust system not adequately supported (7.1.1)

**MOT #3** 2016-04-21 12:39**MOT test number** 756050736838**Result** ✓ Passed**Advice** Front cover insecure ????**Advice** Covers trays and sill covers fitted not allowing full inspection**MOT #2** 2016-04-21 12:39**MOT test number** 807821987347**Result** ✗ Failed**Advice** Front cover insecure ????**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Covers trays and sill covers fitted not allowing full inspection**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #1** 2016-04-21 10:17**MOT test number** 212201454762**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear brake application uneven (3.7.B.2)**Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
14 March 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	14 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>KM13DXE</b>
Plate since	2019-09-29
Current registration	<b>KM13DXE</b>
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2013-04-25
Last registration	2024-03-12
Complete history	<a href="#">See info</a>



Registration #1	2013-04-25	19 mi
Registration #2	2016-04-21	42.655 mi
Registration #3	2016-04-21	42.659 mi
Registration #4	2016-04-21	42.659 mi
Registration #5	2017-03-22	54.284 mi
Registration #6	2017-03-22	54.284 mi
Registration #7	2018-04-19	62.981 mi
Registration #8	2019-03-15	71.303 mi
Registration #9	2019-03-15	71.303 mi
Registration #10	2019-03-15	71.303 mi
Registration #11	2019-03-15	71.303 mi
Registration #12	2019-03-15	71.303 mi
Registration #13	2019-03-15	71.303 mi
Registration #14	2019-03-15	71.303 mi
Registration #15	2019-03-15	71.303 mi
Registration #16	2019-03-15	71.303 mi
Registration #17	2019-03-15	71.303 mi
Registration #18	2019-03-15	71.303 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFS0006719