




report date: 2024-03-28

General information

Make	MINI
Model	ROADSTER COOPER HIGHGATE
Colour	Green
Year of manufacture	2014
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E








Internet history

Entry 2

Date 2023-04-28

Pictures 12

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date 2022-05-26

Pictures 14

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

**MOT history**

MOT expiry date	2024-12-13
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #8	2023-12-11 12:48
MOT test number	481358431821
Result	✓ Passed
Next expiry date	2024-12-13
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #7	2022-12-02 13:48
MOT test number	142550999318
Result	✓ Passed

MOT #6	2021-12-14 16:26
MOT test number	843487459750
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2021-12-14 14:20
MOT test number	796732015716
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Minor	Offside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #4** 2020-11-05 15:32**MOT test number** 684123873893**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2019-05-31 09:20**MOT test number** 387865307566**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2018-06-15 08:03**MOT test number** 789838081567**Result** ✓ Passed**MOT #1** 2017-09-30 12:04**MOT test number** 201644796559**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
13 December 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-09-30
Last registration	2023-12-11
Complete history	See info



Registration #1	2014-09-30	20 mi
Registration #2	2017-09-30	26.101 mi
Registration #3	2018-06-15	27.067 mi
Registration #4	2019-05-31	35.425 mi
Registration #5	2020-11-05	44.200 mi
Registration #6	2021-12-14	48.355 mi
Registration #7	2022-05-20	50.277 mi
Registration #8	2022-05-20	50.277 mi
Registration #9	2022-05-20	50.277 mi
Registration #10	2022-05-20	50.277 mi
Registration #11	2022-05-20	50.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1165 kg
Max. allowed weight	1595 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats 4

Number of axles	2
Engine number	A309J692