





report date: 2024-03-29

### General information

Make	BMW
Model	118 420D M SPORT GRAN COUPE
Colour	Blue
Year of manufacture	2017
Top speed	144 mph
Gearbox	8 speed automatic

# Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

### Internet history

### Entry 2

Date 2023-11-28

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-01-28	
Pictures	10	
Listing price	<u>View report</u>	









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-04
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #5	2023-09-30 08:28
MOT test number	982366456625
Result	✓ Passed
Next expiry date	2024-10-04
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2022-10-01 07:51
MOT test number	937002611438
Result	<b>✓</b> Passed

MOT #3		2021-10-05 08:16
MOT test	number	654264374780
Result		<b>✓</b> Passed
Advice	Gearbox drive flange seal seaping oil	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Factory covers fitted not allowing a full inspection of some components	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2021-10-04 10:25

**MOT test number** 604020374895

Result X Failed

**Fail** Nearside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))

Advice Gearbox drive flange seal seaping oil

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Factory covers fitted not allowing a full inspection of some components

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #1** 2020-10-05 14:39

MOT test number 203940195597

**Result** ✓ Passed

CarCheck.co.uk page 4/11



WV67FZB report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	4 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>		ve?
*********		
********		
***************************************		
	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



**NV67FZB** 

report date: 2024-03-29

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-07
Last registration	2023-09-30
Complete history	See info



Registration #1	2017-09-07	26 mi
Registration #2	2020-10-05	26.240 mi
Registration #3		11.777 es
Registration #4	2021-10-04	34.603 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1825 mm
Height	1397 mm
Length	4638 mm
Wheel base	2810 mm
Kerb weight	1540 kg
Max. allowed weight	2100 kg

### Additional information

Fuel tank capacity	57 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number 71629825