



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Grey
Year of manufacture	2008
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-18
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-15
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	34
Total items failed	7

MOT #19	2023-07-12 15:07
MOT test number	568652336929
Result	✓ Passed
Next expiry date	2024-07-15

MOT #18	2023-07-12 10:55
MOT test number	247657114979
Result	✗ Failed
Fail	Exhaust has a major leak of exhaust gases middle pipe broken (6.1.2 (a))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Emissions unable to be completed (8.2.1.2 (d))

MOT #17	2022-07-16 13:45
MOT test number	885199747440
Result	✓ Passed
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened Both Sides (1.1.14 (a) (ii))
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #16** 2021-07-15 15:34**MOT test number** 203093655773**Result** ✓ Passed**MOT #15** 2020-11-04 17:08**MOT test number** 721735663307**Result** ✓ Passed

- Advice** Oil leak, but not excessive sump corroded (8.4.1 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases system corroded (6.1.2 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2020-10-27 12:54**MOT test number** 729013433211**Result** ✗ Failed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases system corroded (6.1.2 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive sump corroded (8.4.1 (a) (i))

**MOT #13** 2019-10-25 11:08**MOT test number** 689571601119**Result** ✓ Passed**Advice** Front tyres down to 3mm approx tread**Advice** Rear exhaust rear silencer corroded**MOT #12** 2018-10-22 16:38**MOT test number** 830171124584**Result** ✓ Passed**Advice** Rear exhaust silencer outer casing corroded**MOT #11** 2018-10-22 10:07**MOT test number** 562163973842**Result** ✗ Failed**Fail** Nearside Front Lower Anti-roll bar linkage ball joint excessively worn link rod (5.3.4 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Rear exhaust silencer outer casing corroded**MOT #10** 2017-10-23 08:07**MOT test number** 555280660104**Result** ✓ Passed**Advice** Rear silencer outer casing corroded

**MOT #9** 2016-11-08 10:48**MOT test number** 906145090800**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit + cracking sidewall (4.1.E.1)**Advice** Rear silencer outer casing corroded**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear tyre perished/cracked sidewall**MOT #8** 2015-11-05 09:19**MOT test number** 769066049047**Result** ✓ Passed**Advice** Rear silencer outer casing corroded**MOT #7** 2014-10-27 12:17**MOT test number** 637080104388**Result** ✓ Passed**MOT #6** 2013-11-21 16:44**MOT test number** 237675623397**Result** ✓ Passed**MOT #5** 2013-11-21 16:44**MOT test number** 308825523372**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on main beam (1.7.5a)



MOT #4 2013-06-18 11:00

MOT test number 536709863173

Result ✓ Passed

Notice Items removed from driver's view prior to test

MOT #3 2012-07-17 15:52

MOT test number 935439892150

Result ✓ Passed

MOT #2 2011-08-25 10:37

MOT test number 878817031292

Result ✓ Passed

Notice Nail in nearside rear tyre

MOT #1 2011-06-17 14:15

MOT test number 895088161103

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
15 July 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	15 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	CA08XYX
Plate since	2024-03-28
Current registration	CA08XYX
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-08-14
Last registration	2023-07-12
Complete history	See info



Registration #1	2008-08-14	23 mi
Registration #2	2011-06-17	16.318 mi
Registration #3	2011-08-25	17.084 mi
Registration #4	2012-07-17	20.034 mi
Registration #5	2013-06-18	23.898 mi
Registration #6	2013-11-21	25.394 mi
Registration #7	2014-10-27	32.574 mi
Registration #8	2015-11-05	40.357 mi
Registration #9	2016-11-08	46.903 mi
Registration #10	2016-11-08	46.903 mi
Registration #11	2016-11-08	46.903 mi
Registration #12	2016-11-08	46.903 mi
Registration #13	2016-11-08	46.903 mi
Registration #14	2016-11-08	46.903 mi
Registration #15	2016-11-08	46.903 mi
Registration #16	2016-11-08	46.903 mi
Registration #17	2016-11-08	46.903 mi
Registration #18	2016-11-08	46.903 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	4708035