





General information

20D M SPORT
iph
conds
ed Manual
1

Engine & fuel consumption

Power	174 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D







MOT history

MOT expiry date	2021-02-09
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	36
Total items failed	19

MOT #15	2020-02-10 13:48
MOT test number	213883686407
Result	✓ Passed
Next expiry date	2021-02-09
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Tpm light on	
Advice Knocking from nearside rear shock	
Advice Heat shield loose over rear box	





MOT #14	2020-02-06 12:03
MOT test number	814842619687
Result	🗙 Failed
Advice Knocking from nearside rear shock	
Advice Heat shield loose over rear box	
FailParking brake efficiency below requirements (1.4.2 (a) (i))	
FailNearside Front Direction indicator incorrect colour (4.4.3 (a))	
Fail Nearside Rear Shock absorbers likely to become detached (5.3.2 (a) (ii))	
Fail Offside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice Tpm light on	
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Direction indicator incorrect colour (4.4.3 (a))	

MOT #13	2019-01-15 13:41
MOT test number	395029314288
Result	✓ Passed





MOT #12	2019-01-14 10:15
MOT test number	700745268973
Result	🗙 Failed
Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
Advice Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))	
Fail Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Fail Nearside Front Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Nearside Front Service brake excessively binding (1.2.1 (f))	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #11	2017-04-28 08:57
MOT test number	287890743718
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #10	2017-04-27 09:09
MOT test number	680259842147
Result	🗙 Failed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)	
Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
Fail Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)	





MOT #9		2016-04-30 11:24
MOT test	number	890048027518
Result		✓ Passed
Advice	Offside rear brake disc is becoming wasted through corrosion	
MOT #8	number	2015-04-16 12:57
MOT test	number	765616405103
Result		✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weake	ned (3.5.1i)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakene	ed (3.5.1i)
MOT #7		2015-04-09 12:07

MOT #7	2015-04-09 12:07
MOT test number	429739095099
Result	🗙 Failed
Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weake	ened (3.5.1i)
Fail Nearside Inner Rear Upper Suspension arm has excessive play in a pin/bush	(2.4.G.2)
Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened	ed (3.5.1i)
Fail Offside Outer Rear Lower Suspension arm has excessive play in a pin/bush ((2.4.G.2)

MOT #6		2014-05-22 12:07
MOT test	number	217572644453
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Engine covers fitted obscuring some components in the engine bay	





MOT #5	2014-05-19 11:49
MOT test number	216469134451
Result	🗙 Failed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice Under-trays fitted obscuring some underside components	
Fail Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice Engine covers fitted obscuring some components in the engine bay	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2013-05-09 11:03
MOT test number	476349623163
Result	✓ Passed

MOT #3		2011-09-16 17:03
MOT test	number	269009151281
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Brake lining(s) wearing thin (3.5.1g)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Brake lining(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #2		2011-09-16 12:08
MOT test	number	817189251268
Result		🗙 Failed
Advice	Nearside Front Brake lining(s) wearing thin (3.5.1g)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Brake lining(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Ne	earside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #1		2010-09-23 15:02
MOT test	number	233876460238
Result		🗸 Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.	1d)





Tax & MOT check

X Untaxed Tax expired: 6 January 2021	X MOT Expired: 9 February 2021
Tax status	Expired at 6 January 2021
Days left	1210 days too late
MOT expiry date	9 February 2021
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Anne
Туре	K K
Damage 2	AMPLE
Damage 2	e et - I - I
Date	S.
Category	AMPT
Туре	

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

1000000	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-09-28
Last registration	2020-02-10
Complete history	See info



Registration #1	2007-09-28	6 mi
Registration #2	2010-09-23	45.666 mi
Registration #3	2011-09-16	60.624 mi
Registration #4	2011-09-16	60.624 mi
Registration #5	2013-05-09	95.384 mi
Registration #6	2014-05-19	104.692 mi
Registration #7	2014-05-22	104.692 mi
Registration #8	2015-04-09	134.634 mi
Registration #9		10.207 mi
Registration #9 Registration #10		10.000 est
		01.000 est 01.000 est 01.000 est
Registration #10		01,000 est 01,000 est 01,000 est 01,000 est
Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est
Registration #10 Registration #11 Registration #12		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #10 Registration #11 Registration #12 Registration #13		0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1748 mm
Height	1421 mm
Length	4239 mm
Wheel base	2660 mm
Kerb weight	1450 kg
Max. allowed weight	1865 kg
Additional information	
Fuel tank capacity	51
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 14/14

Number of axles	2
Engine number	95586577