



report date: 2024-03-29

General information

Make	SUZUKI
Model	GRAND VITARA SZ-T DDIS
Colour	Blue
Year of manufacture	2012
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.870 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





MOT history

MOT expiry date	2024-05-01
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	13
Total items failed	0

MOT #10	2021-11-06 09:38
MOT test number	206016441224
Result	✓ Passed
Next expiry date	2022-11-05
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #9	2020-09-11 11:22
MOT test number	890284503117
Result	✓ Passed
Advice	Rear BACKBOX SHIELD LOOSE BUT NOT LIKELY TO FALL OFF

MOT #8	2019-11-21 16:25
MOT test number	523453642000
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Brake disc worn, pitted or scored, but not seriously weakened all appear to have been stood (1.1.14 (a) (ii))

MOT #7	2019-09-24 08:56
MOT test number	695800821463
Result	✓ Passed
Advice	Engine/under/sill covers

**MOT #6** 2019-09-23 12:06**MOT test number** 770491197632**Result** ✗ Failed

DANGEROUS Front Brake disc in such a condition that it is seriously weakened both, inner faces (1.1.14 (a) (ii))

Advice Engine/under/sill covers

DANGEROUS Front Brake pad(s) less than 1.5 mm thick both sets (1.1.13 (a) (ii))

MOT #5 2018-12-07 09:58**MOT test number** 994689894453**Result** ✓ Passed

Advice Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2017-12-04 17:47**MOT test number** 836604188958**Result** ✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2016-12-06 12:44**MOT test number** 480880368278**Result** ✓ Passed**MOT #2** 2015-11-30 10:25**MOT test number** 956116139274**Result** ✓ Passed

Advice O/s mirror repeater deteriorated. Rear brake pads approx. 60% worn.



MOT #1	2014-12-08 11:52
MOT test number	406852444328
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
1 May 2024

Tax status	Valid until 1 May
Days left	368
MOT expiry date	1 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2012-01-19
Last registration	2021-11-06
Complete history	See info



Registration #1	2012-01-19	25 mi
Registration #2	2014-12-08	13.101 mi
Registration #3	2015-11-30	26.112 mi
Registration #4	2016-12-06	39.774 mi
Registration #5	2017-12-04	54.085 mi
Registration #6	2018-12-07	67.382 mi
Registration #7	2019-05-29	75.277 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2021-11-06	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1695 mm
Length	4500 mm
Max. allowed weight	2170 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	F9QC-017852