



HYUNDAI

DYIIHJF


report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 ACTIVE
Colour	Black
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-07
Pictures	13
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2024-06-28
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	12
Total items failed	7

MOT #14	2023-06-23 14:11
MOT test number	519309812866
Result	✓ Passed
Next expiry date	2024-06-28

MOT #13	2022-06-29 11:44
MOT test number	665683869548
Result	✓ Passed

MOT #12	2022-06-28 15:06
MOT test number	888023437458
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #11	2021-06-29 08:52
MOT test number	277854293348
Result	✓ Passed

**MOT #10**

2021-02-01 14:39

**MOT test number**

660309650069

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2021-02-01 12:02

**MOT test number**

359201280442

**Result**

✗ Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #8**

2020-02-03 10:02

**MOT test number**

420933004777

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** COOLANT LEVEL BELOW MINIMUM**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7**

2019-01-30 16:25

**MOT test number**

904412998028

**Result**

✓ Passed

**MOT #6** 2019-01-30 10:57**MOT test number** 739455085260**Result** ✗ Failed**Advice** NEARSIDE PARK BRAKE MAX EFFORT 46KG**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #5** 2018-02-07 10:00**MOT test number** 491102231650**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2017-01-23 10:54**MOT test number** 677073273860**Result** ✓ Passed**MOT #3** 2016-02-01 09:00**MOT test number** 906804476341**Result** ✓ Passed**MOT #2** 2015-02-05 15:55**MOT test number** 257876035087**Result** ✓ Passed**MOT #1** 2014-02-25 15:03**MOT test number** 135306654452**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
28 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	28 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-21
Last registration	2023-06-23
Complete history	<a href="#">See info</a>



Registration #1	2011-03-21	21 mi
Registration #2	2014-02-25	14.662 mi
Registration #3	2015-02-05	21.089 mi
Registration #4	2016-02-01	25.962 mi
Registration #5	2017-01-23	32.648 mi
Registration #6	2018-02-07	39.873 mi
Registration #7	2019-01-30	45.947 mi
Registration #8	2019-01-30	45.950 mi
Registration #9	2019-01-30	45.950 mi
Registration #10	2019-01-30	45.950 mi
Registration #11	2019-01-30	45.950 mi
Registration #12	2019-01-30	45.950 mi
Registration #13	2019-01-30	45.950 mi
Registration #14	2019-01-30	45.950 mi
Registration #15	2019-01-30	45.950 mi
Registration #16	2019-01-30	45.950 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FABZ370121