





report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 280 SWB P/V
Colour	Blue
Year of manufacture	2003
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	230 Nm at 2.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/11



EGO3SGZ report date: 2024-03-28

MOT history

MOT expiry date	2020-12-10
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	10
Total items failed	3

MOT #14	2019-06-11 08:51	
MOT test number	129999727052	
Result	✓ Passed	
Next expiry date	2020-12-10	
Advice Nearside Rear Vehicle structure is fractured but structural rigidity is not significantly reduced (6.1.1 (a) (i))		

MOT #13		2019-04-09 12:25
MOT test	number	565508942866
Result		× Failed
DANGER	OUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3	3 (e))
MAJOR	Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3	(b) (ii))
Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))		
MAJOR	Windscreen washer not working (3.5 (a))	
MAJOR reducing s	Offside Rear Suspension component mounting prescribed area excessively cructural strength chassis (5.3.6 (a) (i))	corroded significantly

MOT #12		2018-03-17 10:51
MOT test	number	789855770552
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Rear wheel bearing has slight play (2.6.2)	

CarCheck.co.uk page 2/11



Result

EG03SGZ

report date: 2024-03-28

✓ Passed

MOT #11 2016-09-24 09:06

MOT test number 695799378016

Result ✓ Passed

MOT #10 2016-09-24 09:06

MOT test number 311767603448

Result X Failed

Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)

Pass with rectification Nearside Obligatory mirror seriously obscured affecting the rear view (8.1.2a)

Pass with rectification Offside Rear Registration plate lamp not working (1.1.C.1d)

MOT #9 2015-11-18 10:20

MOT test number 962834887582

Advice Rear chassis rails have corrosion forming

Advice Real chassis rails have corresion forming

MOT #8 2014-09-03 10:45

MOT test number 575476644266

Result \sqrt{Passed}

Advice Front Power steering component(s) has slight seepage from a component (2.3.3b)

MOT #7 2014-02-04 11:06

MOT test number 118535634060

MOT #6 2012-09-03 10:26

MOT test number 147077942250

Result
✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #5	2011-08-05 12:46
MOT test number	237477011288
Result	✓ Passed
MOT #4	2010-08-02 15:20
MOT test number	680034510285
Result	✓ Passed
MOT #3	2009-07-23 16:09
MOT test number	260264209292
Result	✓ Passed
MOT #2	2007-09-08 10:41
MOT test number	371301957204
Result	✓ Passed
MOT #1	2006-08-02 13:51
MOT test number	500304516208
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check





Expired: 10 December 2020

Tax status Expired at 23 January 2021

Days left 1191 days too late

MOT expiry date 10 December 2020

Full MOT history See MOT history

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this FORD? How many owners defined the current and see all owner registrations. Download the full report in the premium report and see all owner registrations.	
manage of the same	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	IK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2003-08-01
Last registration	2019-06-11
Complete history	See info



Registration #1	2003-08-01	20 mi
Registration #2	2006-08-02	23.532 mi
Registration #3	2007-09-08	33.586 mi
Registration #4	2009-07-23	52.447 mi
Registration #5	2010-08-02	61.377 mi
Registration #6	2011-08-05	65.609 mi
Registration #7	2012-09-03	72.130 mi
Registration #8	2014-02-04	76.924 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Dimensions & weight

Width	2360 mm
Height	1970 mm
Length	4834 mm

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Engine number	2A66621

CarCheck.co.uk page 11/11