



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SPORT TDI (100BHP)
Colour	Red
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	240 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	68.9 mpg
Consumption combined	56.5 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	4
Listing price	View report



source: [yesauto.com](#)

**MOT history**

MOT #14	2020-10-15 13:39
MOT test number	430416832607
Result	✓ Passed
Next expiry date	2021-10-27
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear silencer outer skin corroded, exhaust not leaking gases

MOT #13	2019-10-21 09:11
MOT test number	477026100973
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #12	2018-10-24 11:10
MOT test number	939070673073
Result	✓ Passed
Advice	Play in steering rack inner joint(s) both sides
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #11	2018-10-24 11:10
MOT test number	553430346281
Result	✗ Failed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Play in steering rack inner joint(s) both sides
Pass with rectification	Rear Exhaust shield missing where fitted as original equipment creating a risk of fire hanging down (6.1.3 (e))



MOT #10 2017-10-26 14:53

MOT test number 329034139176

Result ✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Play in steering rack inner joint(s)

Advice Front brake fluctuating, but not excessively (3.7.B.3)

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

MOT #9 2017-10-26 13:27

MOT test number 796524982929

Result ✗ Failed

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice Front brake fluctuating, but not excessively (3.7.B.3)

Advice Play in steering rack inner joint(s)

Fail Offside Rear coil spring broken (2.4.C.1a)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #8 2016-10-12 08:47

MOT test number 862174334527

Result ✓ Passed

Advice Front front brake fluctuating, but not excessively (3.7.B.3)

Advice Play in steering rack inner joint(s)

**MOT #7** 2016-10-11 13:54**MOT test number** 744834744566**Result** ✗ Failed**Advice** Play in steering rack inner joint(s)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Front front brake fluctuating, but not excessively (3.7.B.3)**MOT #6** 2015-09-30 08:16**MOT test number** 891653622163**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Slight play in both front steering arms**Advice** Both number plates have a space in between the letter 'h' and 'j' but not likely to be misread**Advice** Front pads starting to wear thin (5mm)**Advice** Rear discs slightly corroded**Advice** Back box outer skin peeling**MOT #5** 2014-10-24 10:29**MOT test number** 788347994238**Result** ✓ Passed**MOT #4** 2013-10-28 14:26**MOT test number** 605451103344**Result** ✓ Passed

**MOT #3** 2012-10-26 09:20**MOT test number** 365090702332**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2 2011-10-20 09:15**MOT test number** 148093491210**Result** ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2010-10-25 09:11**MOT test number** 134058090291**Result** ✓ Passed

Notice Nearside front wishbone bush slight wear

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<div><div></div><div>*****</div></div>
Plate since	2019-06-29
Current registration	<div><div></div><div>*****</div></div>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-10-27
Last registration	2020-10-15
Complete history	See info



Registration #1	2007-10-27	15 mi
Registration #2	2010-10-25	54.425 mi
Registration #3	2011-10-20	71.134 mi
Registration #4	2012-10-26	83.438 mi
Registration #5	2013-10-28	95.068 mi
Registration #6	2014-10-24	102.516 mi
Registration #7	2015-09-30	107.089 mi
Registration #8	2016-10-11	112.897 mi
Registration #9	2016-10-12	112.900 mi
Registration #10	2016-10-12	112.900 mi
Registration #11	2016-10-12	112.900 mi
Registration #12	2016-10-12	112.900 mi
Registration #13	2016-10-12	112.900 mi
Registration #14	2016-10-12	112.900 mi
Registration #15	2016-10-12	112.900 mi
Registration #16	2016-10-12	112.900 mi
Registration #17	2016-10-12	112.900 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

AXR575251