



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 SE SPORT V50
Colour	Blue
Year of manufacture	2006
Top speed	124 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-28
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-03
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	31
Total items failed	5

MOT #19	2023-05-12 14:16
MOT test number	828324447756
Result	✓ Passed
Next expiry date	2024-06-03

MOT #18	2023-05-11 14:08
MOT test number	809377730721
Result	✗ Failed

- MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge wear close to cords/ply 205/55r16 (5.2.3 (e))
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Fuel cap/sealing device ineffective (6.1.3 (b) (i))
- MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #17** 2022-05-31 11:15**MOT test number** 643069189464**Result** ✓ Passed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #16** 2022-05-31 11:15**MOT test number** 460399350773**Result** ✗ Failed**Pass with rectification** Nearside Front Obligatory mirror does not provide a view to the rear (3.3 (c))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #15** 2021-06-04 14:07**MOT test number** 447784233431**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #14** 2020-07-31 09:32**MOT test number** 537168137593**Result** ✓ Passed**MOT #13** 2019-05-08 11:33**MOT test number** 328037785906**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Power steering ram has slight seepage from a joint rack ends damp (2.1.5 (a))

**MOT #12** 2018-04-26 11:15**MOT test number** 274126831781**Result** ✓ Passed**MOT #11** 2017-04-26 09:19**MOT test number** 351323155587**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #10** 2016-04-26 10:52**MOT test number** 297227609631**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9** 2015-04-28 13:55**MOT test number** 159758715194**Result** ✓ Passed**MOT #8** 2014-05-20 10:51**MOT test number** 788950344187**Result** ✓ Passed

**MOT #7** 2013-05-23 16:10**MOT test number** 248013843425**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Offside rear tyre cracking (inner tyre wall)**Notice** Nail in nearside front tyre**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2013-05-23 14:28**MOT test number** 255473243115**Result** ✗ Failed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Offside rear tyre cracking (inner tyre wall)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Nail in nearside front tyre**MOT #5** 2012-05-01 11:25**MOT test number** 418002822128**Result** ✓ Passed**Notice** Both front and offside rear tyres cracking**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2012-05-01 11:25**MOT test number** 517272922184**Result** ✗ Failed**Notice** Both front and offside rear tyres cracking**Pass with rectification** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Direction indicators incorrect colour (1.4.A.2f)**MOT #3** 2011-05-03 09:33**MOT test number** 237103721174**Result** ✓ Passed**MOT #2** 2010-05-06 12:27**MOT test number** 230536520156**Result** ✓ Passed**MOT #1** 2009-04-14 13:54**MOT test number** 214644109432**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
3 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	3 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-04-26
Last registration	2023-05-12
Complete history	See info



Registration #1	2006-04-26	23 mi
Registration #2	2009-04-14	22.393 mi
Registration #3	2010-05-06	29.927 mi
Registration #4	2011-05-03	34.700 mi
Registration #5	2012-05-01	39.890 mi
Registration #6	2013-05-23	44.659 mi
Registration #7	2013-05-23	44.659 mi
Registration #8	2014-05-20	48.579 mi
Registration #9	2015-04-28	52.133 mi
Registration #10	2016-04-26	56.325 mi
Registration #11	2016-05-20	56.325 mi
Registration #12	2016-05-20	56.325 mi
Registration #13	2016-05-20	56.325 mi
Registration #14	2016-05-20	56.325 mi
Registration #15	2016-05-20	56.325 mi
Registration #16	2016-05-20	56.325 mi
Registration #17	2016-05-20	56.325 mi
Registration #18	2016-05-20	56.325 mi
Registration #19	2016-05-20	56.325 mi
Registration #20	2016-05-20	56.325 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	41532