



HYUNDAI



**MV63NSK**


report date: 2024-03-29

## General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I





## MOT history

MOT expiry date	2021-08-31
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	6
Total items failed	7

MOT #7	2020-09-01 08:17
MOT test number	670998838846
Result	✓ Passed
Next expiry date	2021-08-31

MOT #6	2020-08-27 16:26
MOT test number	303474781759
Result	✗ Failed
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #5	2019-08-29 09:54
MOT test number	270420653087
Result	✓ Passed

MOT #4	2018-08-28 09:34
MOT test number	220826378031
Result	✓ Passed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #3** 2017-08-31 11:10**MOT test number** 202930247063**Result** ✓ Passed**MOT #2** 2017-08-30 08:58**MOT test number** 187429438398**Result** ✗ Failed

- Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Rear registration plate deteriorated (6.3.1d)
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #1** 2016-08-27 08:24**MOT test number** 602091815592**Result** ✓ Passed

- Advice** Both front tyres getting low 235/60/18 107W
- Advice** Engine covers fitted
- Advice** All brake discs slightly worn
- Advice** Windscreen chipped both zones
- Advice** Damage to nearside of vehicle



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2013-09-01
Last registration	2020-09-01
Complete history	<a href="#">See info</a>



Registration #1	2013-09-01	14 mi
Registration #2	2016-08-27	126.718 mi
Registration #3	2017-08-30	168.746 mi
Registration #4	2017-08-31	168.750 mi
Registration #5	2020-09-01	168.750 mi
Registration #6	2020-09-01	168.750 mi
Registration #7	2020-09-01	168.750 mi
Registration #8	2020-09-01	168.750 mi

More info >





Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1880 mm
Height	1690 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	2001 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Engine number**

D4HBDU876742