





report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE SPORT
Colour	Blue
Year of manufacture	2007
Top speed	134 mph
	<u> </u>
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-11

Pictures 23

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-12-05
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	16
Total items failed	5

MOT #17	2023-11-29 11:59
MOT test number	262262525341
Result	✓ Passed
Next expiry date	2024-12-05

MOT #16	2022-12-01 14:51
MOT test number	401155369299
Result	√ Passed

MOT #15	2021-12-04 13:32
MOT test number	794461387825
Result	✓ Passed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #14	2020-11-27 14:53
MOT test number	128380991658
Result	✓ Passed
Advice Sill covers fitted	
Advice Underbody covers fitted	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13

MOT test number

951346909376

Result

Advice Underbody covers fitted

MOT #12 2018-11-30 11:19 **MOT** test number 993679068351 Result ✓ Passed **MOT #11** 2017-11-29 13:41 **MOT** test number 938198499770 Result ✓ Passed **Advice** Under body covers fitted Advice Front Brake pad(s) wearing thin (3.5.1g) Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #10

MOT test number

Result

Advice Advise under body covers fitted

2016-12-02 09:52

374579918342

✔ Passed

MOT #9

MOT test number

479915482227

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8 2015-11-23 11:46

MOT test number 129944332780

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #7 2014-12-05 13:12

MOT test number 627169234381

Result ✓ Passed

MOT #6 2013-11-25 12:33

MOT test number 546309423372

Result \rightarrow Passed

MOT #5 2012-12-06 09:06

MOT test number 218451242395

Result
✓ Passed

Advice Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2012-11-29 10:24

MOT test number 227344532372

Result X Failed

Advice Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Centre Stop lamp not working (1.2.1b)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number

247229671226

Result

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-10-21 14:36
MOT test number	104284690219
Result	✓ Passed

CarCheck.co.uk page 6/13



VK57GOX report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	5 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



VK57GOX report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

HARMAN CO.	

THE STREET STREET	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	IK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



VK57GOX report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-13
Last registration	2023-11-29
Complete history	See info



Registration #1	2007-09-13	11 mi
Registration #2	2010-10-21	45.992 mi
Registration #3	2011-10-06	61.084 mi
Registration #4	2011-10-06	61.084 mi
Registration #5	2012-11-29	85.477 mi
Registration #6	2012-12-06	85.479 mi
Registration #7	2013-11-25	93.937 mi
Registration #8	2014-12-05	101.282 mi
Registration #9	2015-11-23	114.293 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		111.777 mg

More info >

CarCheck.co.uk page 12/13



VK57GOX report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

-		_		
-I)ım	ensions	. ბ	weia	nt

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1778 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	564081

CarCheck.co.uk page 13/13