



RENAULT

**SD570KG**


report date: 2024-03-29

General information

Make	RENAULT
Model	CLIO DYNAMIQUE 16V TURBO
Colour	Black
Year of manufacture	2007
Top speed	114 mph
0 - 100 km/h	13.4 seconds
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 kW / 75 HP / 100 BHP
Max. torque	105 Nm at 4.250 rpm
Engine capacity	1.149 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2025-02-25
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	27
Total items failed	13

MOT #20	2024-02-22 13:24
MOT test number	342240572249
Result	✓ Passed
Next expiry date	2025-02-25
Advice	Play in both front lower arms
Advice	Slight oil leak
Advice	Front pads low

MOT #19	2023-02-22 17:04
MOT test number	583274654475
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #18**

2023-02-22 12:56

**MOT test number**

562822021301

**Result****✗ Failed****Fail**

Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice**

Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**Fail**

Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**Fail**

Nearside Headlamp aim unable to be tested (4.1.2 (b))

**Advice**

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Advice**

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Fail**

Nearside Headlamp light intensity severely reduced (4.1.4 (a))

**Fail**

Offside Front Position lamp not working (4.2.1 (a) (ii))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17**

2022-02-21 12:26

**MOT test number**

642970982058

**Result****✓ Passed****MOT #16**

2021-02-18 10:22

**MOT test number**

144804030624

**Result****✓ Passed****MOT #15**

2021-02-16 08:21

**MOT test number**

547968939671

**Result****✗ Failed****Fail**

Brake lever has insufficient reserve travel (1.1.2 (a))

**MOT #14** 2020-02-19 14:31**MOT test number** 450812189532**Result** ✓ Passed**MOT #13** 2019-02-25 17:03**MOT test number** 227421549219**Result** ✓ Passed**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #12** 2018-02-24 10:56**MOT test number** 385800038117**Result** ✓ Passed**MOT #11** 2017-02-16 10:47**MOT test number** 952564591761**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #10** 2016-02-22 16:26**MOT test number** 227282597738**Result** ✓ Passed

**MOT #9** 2016-02-22 13:42**MOT test number** 548105194698**Result** ✗ Failed

- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Lower Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #8** 2015-02-26 12:02**MOT test number** 186237955437**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7** 2014-02-26 16:17**MOT test number** 125997054473**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

**MOT #6** 2013-02-25 11:26**MOT test number** 318546853025**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2012-09-18 12:44**MOT test number** 989902462232**Result** ✓ Passed**MOT #4** 2012-09-18 10:12**MOT test number** 269992162217**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #3** 2011-08-30 11:47**MOT test number** 385852441279**Result** ✓ Passed**MOT #2** 2011-08-27 09:53**MOT test number** 685779431228**Result** ✗ Failed**Fail** Offside Front coil spring incomplete (2.4.C.1a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Front brake discs worn**MOT #1** 2010-08-27 09:10**MOT test number** 303399930249**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
25 February 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	25 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,200
Auction value	£ 19,200
Average private trade value	£ 19,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>SD570KG</b>
Plate since	2019-03-29
Current registration	<b>SD570KG</b>
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-26
Last registration	2024-02-22
Complete history	<a href="#">See info</a>



Registration #1	2007-09-26	12 mi
Registration #2	2010-08-27	12.800 mi
Registration #3	2011-08-27	18.907 mi
Registration #4	2011-08-30	18.907 mi
Registration #5	2012-09-18	26.185 mi
Registration #6	2012-09-18	26.185 mi
Registration #7	2013-02-25	27.100 mi
Registration #8	2014-02-26	31.799 mi
Registration #9	2015-02-26	37.539 mi
Registration #10	2016-02-22	45.318 mi
Registration #11	2016-02-22	45.319 mi
Registration #12	2016-02-22	45.319 mi
Registration #13	2016-02-22	45.319 mi
Registration #14	2016-02-22	45.319 mi
Registration #15	2016-02-22	45.319 mi
Registration #16	2016-02-22	45.319 mi
Registration #17	2016-02-22	45.319 mi
Registration #18	2016-02-22	45.319 mi
Registration #19	2016-02-22	45.319 mi
Registration #20	2016-02-22	45.319 mi
Registration #21	2016-02-22	45.319 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1720 mm
Height	1497 mm
Length	4032 mm
Wheel base	2472 mm
Kerb weight	1080 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	F009933