



UK

EIL JH

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE DESIGN TDI BLUEMOTION TECHNOLOGY DSG
Colour	Red
Year of manufacture	2015
Top speed	123 mph
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	56.5 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 2

Date	2023-02-13
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

Entry 1

Date	2021-01-28
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2024-09-21
<b>MOT pass rate</b>	88 %
<b>MOT passed</b>	7
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	11
<b>Total items failed</b>	2

<b>MOT #8</b>	2023-09-22 08:26
<b>MOT test number</b>	906232385176
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-09-21
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge Tread depth is 2.4 mm (5.2.3 (e))

<b>MOT #7</b>	2022-09-14 08:56
<b>MOT test number</b>	724660287859
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

<b>MOT #6</b>	2021-09-17 12:16
<b>MOT test number</b>	327549856742
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge wearing at inner edge of tread (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge wearing at inner edge of tread (5.2.3 (e))



<b>MOT #5</b>	2020-09-16 13:01
<b>MOT test number</b>	601312548040
<b>Result</b>	✓ Passed
<b>Advice</b>	Service due in 10 days

<b>MOT #4</b>	2020-09-15 09:50
<b>MOT test number</b>	880774155623
<b>Result</b>	✗ Failed
<b>Fail</b>	Rear fog lamp not working (4.5.1 (a) (ii))
<b>Fail</b>	Offside Front Inner Suspension arm pin or bush excessively worn inner rear bush failed (5.3.4 (a) (i))
<b>Advice</b>	Service due in 10 days

<b>MOT #3</b>	2019-09-19 16:08
<b>MOT test number</b>	420392862321
<b>Result</b>	✓ Passed

<b>MOT #2</b>	2019-04-12 10:10
<b>MOT test number</b>	476531265360
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2018-03-10 11:31
<b>MOT test number</b>	745392355852
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
21 September 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	21 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>E1LJH</b>
Plate since	2024-03-29
Current registration	 <b>E1LJH</b>
Plate since	2024-03-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-04-01
Last registration	2023-09-22
Complete history	<a href="#">See info</a>



Registration #1	2015-04-01	18 mi
Registration #2	2018-03-10	20.846 mi
Registration #3	2019-04-12	26.445 mi
Registration #4	2019-09-19	26.775 mi
Registration #5	2020-09-15	30.786 mi
Registration #6	2020-09-16	30.818 mi
Registration #7	2023-09-22	35.277 mi
Registration #8	2023-09-22	35.277 mi
Registration #9	2023-09-22	35.277 mi
Registration #10	2023-09-22	35.277 mi
Registration #11	2023-09-22	35.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2021 mm
Height	1473 mm
Length	4278 mm
Wheel base	2540 mm
Kerb weight	1529 kg
Max. allowed weight	1910 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

**Number of axles**

2

**Engine number**

CUUB018610