



MC08ZYX

report date: 2024-03-28

General information

Make	AUDI
Model	A5 TDI
Colour	Black
Year of manufacture	2008
Top speed	144 mph
0 - 60 mph	7.6 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	190 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	2.698 cc
Cylinders	6
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	179 g/km
CO2 label	I





MOT history

MOT expiry date	2024-12-03
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	62
Total items failed	18

MOT #20	2023-12-01 15:54
MOT test number	484949265496
Result	✓ Passed
Next expiry date	2024-12-03
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
Minor	Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #19	2023-12-01 15:54
MOT test number	871135783119
Result	✗ Failed
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
Pass with rectification	Central Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))
Minor	Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #18**

2022-12-03 14:34

MOT test number

721918644594

Result

✓ Passed

Advice Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

Minor Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #17

2022-12-03 13:07

MOT test number

574529388230

Result

✗ Failed

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Minor Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Pass with rectification Central Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

Advice Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

**MOT #16** 2021-11-27 10:39**MOT test number** 795722265070**Result** ✓ Passed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Sill (5.3.6 (a) (i))

MOT #15 2021-11-26 09:49**MOT test number** 610141471562**Result** ✗ Failed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Sill (5.3.6 (a) (i))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #14 2020-12-04 17:09**MOT test number** 701504755507**Result** ✓ Passed**MOT #13** 2020-12-02 18:32**MOT test number** 499737736670**Result** ✗ Failed

- Fail** Front Tyre tread depth below requirements of 1.6mm Both sides (5.2.3 (e))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge Edges Worn (5.2.3 (e))



MOT #12	2019-06-01 11:43
MOT test number	521300389069
Result	✓ Passed

MOT #11	2017-12-21 14:40
MOT test number	501202936525
Result	✓ Passed
Advice	Under tray fitted

MOT #10	2016-12-21 14:36
MOT test number	683604631959
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #9	2016-12-21 09:45
MOT test number	785522832002
Result	✗ Failed
Fail	Nearside Headlamp aim too low (1.8)
Fail	Headlamp levelling device obviously defective (1.7.2)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Headlamp aim too low (1.8)
Fail	Headlamp cleaning device inoperative (1.7.2)

**MOT #8**

2015-12-17 16:31

MOT test number

581056633876

Result

✓ Passed

Advice Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit inner edge worn (4.1.E.1)

Advice Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

Advice Offside Rear tyre slightly misshaped

MOT #7

2015-12-17 09:47

MOT test number

662661854141

Result

✗ Failed

Advice Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Headlamp aim too low (1.8)

Advice Offside Rear tyre slightly misshaped

Advice Offside Front Tyre worn close to the legal limit inner edge worn (4.1.E.1)

Advice Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

Fail Offside Headlamp aim too low (1.8)



MOT #6	2014-12-03 15:57
MOT test number	377787734331
Result	✓ Passed
Advice	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Notice	Glow plug lamp flashing
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5	2014-12-03 15:57
MOT test number	147127334330
Result	✗ Failed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Pass with rectification Offside Front Headlamp aim too high (1.8)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Glow plug lamp flashing

Advice Offside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Pass with rectification Nearside Rear Rear position lamp(s) not working (1.1.A.3b)

**MOT #4** 2013-06-19 14:37**MOT test number** 336550973139**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2012-06-14 15:37**MOT test number** 278016162465**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2012-06-14 10:38**MOT test number** 537196462151**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-05-05 11:19**MOT test number** 156175421161**Result** ✓ Passed**Notice** Wiper blades smearing screen



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
3 December 2024

Tax status		Valid until 1 March
Days left		306
MOT expiry date		3 December 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-06-04
Last registration	2023-12-01
Complete history	See info



Registration #1	2008-06-04	13 mi
Registration #2	2011-05-05	25.382 mi
Registration #3	2012-06-14	42.562 mi
Registration #4	2012-06-14	42.562 mi
Registration #5	2013-06-19	55.105 mi
Registration #6	2014-12-03	75.917 mi
Registration #7	2015-12-17	89.385 mi
Registration #8	2015-12-17	89.385 mi
Registration #9	2016-12-21	98.469 mi
Registration #10	2016-12-21	98.469 mi
Registration #11	2016-12-21	98.469 mi
Registration #12	2016-12-21	98.469 mi
Registration #13	2016-12-21	98.469 mi
Registration #14	2016-12-21	98.469 mi
Registration #15	2016-12-21	98.469 mi
Registration #16	2016-12-21	98.469 mi
Registration #17	2016-12-21	98.469 mi
Registration #18	2016-12-21	98.469 mi
Registration #19	2016-12-21	98.469 mi
Registration #20	2016-12-21	98.469 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1854 mm
Height	1372 mm
Length	4625 mm
Wheel base	2751 mm
Kerb weight	1575 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	CAM 013025