



report date: 2024-03-28

General information

Make	KIA
Model	RIO CRDI VR7 ECODYNAMICS
Colour	Black
Year of manufacture	2014
Top speed	99 mph
0 - 60 mph	15.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	170 Nm at 1.500 rpm
Engine capacity	1.120 cc
Cylinders	3
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-06-14
Pictures	3
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-07-11
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	23
Total items failed	4

MOT #10	2023-07-03 10:50
MOT test number	874601182425
Result	✓ Passed
Next expiry date	2024-07-11

MOT #9	2023-07-03 08:16
MOT test number	101026402075
Result	✗ Failed
Advice	Nearside Rear Nail in tyre 185/65/15
Fail	Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))

MOT #8	2022-07-04 12:08
MOT test number	977087885713
Result	✓ Passed
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge 185/65R15 (5.2.3 (e))
Advice	Rear exhaust hanger rusty
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge 185/65R15 (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing 185/65R15 (5.2.3 (d) (ii))
Advice	Rear Exhaust flange rusty

**MOT #7**

2022-07-04 10:53

**MOT test number**

767145458838

**Result****✗ Failed****Advice** Rear exhaust hanger rusty**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge 185/65R15 (5.2.3 (e))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Rear Exhaust flange rusty**Fail** Nearside Front Side repeater incorrect colour (4.4.3 (a))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge 185/65R15 (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 185/65R15 (5.2.3 (d) (ii))**MOT #6**

2021-07-12 08:02

**MOT test number**

455648177986

**Result****✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5**

2021-07-12 08:02

**MOT test number**

697606658333

**Result****✗ Failed****Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4**

2020-06-16 08:43

**MOT test number**

245595633006

**Result****✓ Passed****Advice** Items removed from driver's view prior to test

**MOT #3** 2019-06-11 14:53**MOT test number** 322791734170**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Items removed from driver's view prior to test**MOT #2** 2018-06-08 08:33**MOT test number** 438265451194**Result** ✓ Passed**MOT #1** 2017-06-21 11:53**MOT test number** 980980186814**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brakes binding slightly**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
11 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	11 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>WM14SMX</b>
Plate since	2019-03-28
Current registration	<b>WM14SMX</b>
Plate since	2019-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-06-30
Last registration	2023-07-03
Complete history	<a href="#">See info</a>



Registration #1	2014-06-30	23 mi
Registration #2	2017-06-21	72.093 mi
Registration #3	2018-06-08	94.017 mi
Registration #4	2019-06-11	116.133 mi
Registration #5	2020-06-16	134.397 mi
Registration #6	2021-06-20	152.717 mi
Registration #7	2022-06-20	171.037 mi
Registration #8	2023-06-20	189.357 mi
Registration #9	2024-06-20	207.677 mi
Registration #10	2025-06-20	225.997 mi
Registration #11	2026-06-20	244.317 mi
Registration #12	2027-06-20	262.637 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4045 mm
Wheel base	2570 mm
Kerb weight	1255 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D3FAEH328674