



report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER S ALL4
Colour	White
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-07-10
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-31
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	18
Total items failed	1

MOT #11	2023-08-26 09:07
MOT test number	252880546244
Result	✓ Passed
Next expiry date	2024-08-31

MOT #10	2022-08-12 18:54
MOT test number	120105339053
Result	✓ Passed

**MOT #9** 2022-08-09 14:34**MOT test number** 528024142842**Result** ✗ Failed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Minor** Offside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Rear Registration plate does not conform to the specified requirements obscured (0.1 (d))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Front Windscreen wiper blade defective both (3.4 (b) (i))
- MAJOR** Front Headlamp cleaning device for LED or HID headlamp inoperative both (4.1.6 (a) (ii))

MOT #8 2021-08-25 12:02**MOT test number** 117575512688**Result** ✓ Passed**MOT #7** 2020-08-27 12:48**MOT test number** 707640047715**Result** ✓ Passed

- Advice** Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #6** 2020-08-26 12:21**MOT test number** 940396846625**Result** ✗ Failed**Advice** Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**DANGEROUS** Offside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #5** 2019-08-01 10:48**MOT test number** 376656874297**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin uneven wear (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge uneven wear inside edge (5.2.3 (e))**MOT #4** 2018-09-01 08:31**MOT test number** 462941212777**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Front Play in steering rack inner joint(s) slight play both sides**Advice** Offside Front Tyre slightly damaged/valve stem damaged inside (5.2.3 (d) (i))**MOT #3** 2017-07-25 11:32**MOT test number** 819692683824**Result** ✓ Passed**MOT #2** 2016-07-20 11:31**MOT test number** 137651329043**Result** ✓ Passed



MOT #1	2016-07-20 09:31
MOT test number	686159711068
Result	✗ Failed
Fail	Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	EN13PKY
Plate since	2019-03-28
Current registration	EN13PKY
Plate since	2019-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-08-09
Last registration	2023-08-26
Complete history	See info



Registration #1	2013-08-09	24 mi
Registration #2	2016-07-20	36.636 mi
Registration #3	2016-07-20	36.636 mi
Registration #4	2017-07-25	43.456 mi
Registration #5	2018-09-01	54.051 mi
Registration #6	2019-08-01	63.319 mi
Registration #7	2020-08-26	71.336 mi
Registration #8	2023-08-26	71.336 mi
Registration #9	2023-08-26	71.336 mi
Registration #10	2023-08-26	71.336 mi
Registration #11	2023-08-26	71.336 mi
Registration #12	2023-08-26	71.336 mi
Registration #13	2023-08-26	71.336 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Max. allowed weight	1865 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

B221J286