





General information

Make	VOLKSWAGEN
Model	FOX
Colour	Blue
Year of manufacture	2010
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history		
Entry 1		
Date	2021-12-18	
Pictures	0	
Listing price	View report	

source: autotrader.co.uk



MOT history

MOT expiry date	2023-02-27
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	16
Total items failed	16

MOT #16	2022-02-28 13:11
MOT test number	569484099516
Result	✓ Passed
Next expiry date	2023-02-27
Advice Power steering pipe/hose slightly damaged (2	2.1.5 (g) (i))
Advice Surface corrosion on suspension components	

MOT #15	2022-02-15 10:42
MOT test number	693375108493
Result	× Failed
Fail Offside Front Outer Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice Power steering pipe/hose slightly damaged (2.1.5 (g) (i))	
Advice Surface corrosion on suspension components	
Fail Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))	

MOT #14	2021-04-17 10:30
MOT test number	244719190782
Result	✓ Passed





MOT #13	2020-04-24 12:55
MOT test number	123660891664
Result	✓ Passed
MOT #12	2020-04-24 11:13
MOT test number	958015712073
Result	🗙 Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Front Service brake excessively fluctuating (1.2.1 (e))	

MOT #11		2019-04-12 15:33
MOT test	number	858537383028
Result		✓ Passed
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	

MOT #10	2019-04-12 13:56	
MOT test number	254407737405	
Result	🗙 Failed	
Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))		
Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))		

MOT #9	2018-04-10 14:45
MOT test number	895316935795
Result	✓ Passed





MOT #	B	2018-04-10 12:01
MOT te	st number	855900444900
Result		🗙 Failed
Fail	Offside Front coil spring broken (2.4.C.1a)	
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Front Brakes imbalanced across an axle Axle 1 (3.7.B.5b)	

MOT #7	2017-04-21 15:58
MOT test number	763453760146
Result	✓ Passed

MOT #6	5	2017-04-21 11:22
MOT te	st number	745337744251
Result		🗙 Failed
Fail	Exhaust has a major leak of exhaust gases flexi (7.1.2)	
Fail	Offside Headlamp not working on dipped beam (1.7.5a)	
Fail	Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)	
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	

MOT #5	2016-04-23 09:29
MOT test number	832864466771
Result	✓ Passed



NA10UAT
report date: 2024-03-29

МОТ #4	2016-04-22 10:22
MOT test number	407694167758
Result	🗙 Failed
Fail Front Exhaust has a major leak of exhaust gases flexi (7.1.2)	
Fail Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)	
Fail Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)	

MOT #3	2015-04-16 16:13
MOT test	number 737296005104
Result	✓ Passed
Advice	Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)
Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)	
Advice	Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	201-	4-04-04 13:55
MOT test	number 5	76784894064
Result		✓ Passed
Advice	Offside Front Suspension arm has slight play in a track control arm inner bush (2.5.B.2	2b)
Notice	Under-trays fitted obscuring some underside components	
Advice	Nearside Front Suspension arm has slight play in a track control arm inner bush (2.5.E	3.2b)

MOT #1	2013-04-22 10:50
MOT test number	447182213194
Result	✓ Passed
Notice Under-trays fitted obscuring some underside components	



Tax & MOT check

X Untaxed Tax expired: 1 August 2022	X MOT Expired: 27 February 2023
Tax status	Expired at 1 August 2022
Days left	636 days too late
MOT expiry date	27 February 2023
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT ON
Date	*
Category	AMP
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Format maintration	
Carrient registration	
Parla since	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-04-22
Last registration	2022-02-28
Complete history	See info



Registration #1	2010-04-22	22 mi
Registration #2	2013-04-22	37.897 mi
Registration #3	2014-04-04	45.334 mi
Registration #4	2015-04-16	52.979 mi
Registration #5	2016-04-22	60.020 mi
Registration #6	2016-04-23	60.030 mi
Registration #7	2017-04-21	66.457 mi
Registration #8	2017-04-21	66.460 mi
Registration #9	2018-04-10	72.763 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.117 mi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight Width 1660 mm Height 1544 mm Length 3828 mm Wheel base 2465 mm Kerb weight 1069 kg Max. allowed weight 1480 kg Additional information **Fuel tank capacity** 50 I **Fuel delivery Multi-Point Injection** Number of doors 3

Number of seats	4
Number of axles	2
Engine number	CHF 058721