



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2300 L2H1 CDTI SPORTIVE
Colour	White
Year of manufacture	2016
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-23
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-28
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	20
Total items failed	5

MOT #7	2023-09-28 11:45
MOT test number	513252455208
Result	✓ Passed
Next expiry date	2024-09-28
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))

**MOT #6**

2023-09-26 07:57

MOT test number

454374593633

Result

✗ Failed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))

MOT #5

2022-09-22 14:21

MOT test number

399533868563

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**MOT #4** 2022-09-20 10:49**MOT test number** 727523837798**Result** ✗ Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Fail Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #3 2021-09-17 11:46**MOT test number** 427120712170**Result** ✓ Passed**MOT #2** 2020-09-29 12:11**MOT test number** 206151435614**Result** ✓ Passed**MOT #1** 2019-05-30 12:42**MOT test number** 420983096810**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
28 September 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	28 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KR16ZVP
Plate since	2019-03-29
Current registration	 KR16ZVP
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-05-05
Last registration	2023-09-28
Complete history	See info



Registration #1	2016-05-05	28 mi
Registration #2	2019-05-30	39.568 mi
Registration #3	2020-09-29	49.463 mi
Registration #4	2021-09-17	57.187 mi
Registration #5	2023-09-28	57.187 mi
Registration #6	2023-09-28	57.187 mi
Registration #7	2023-09-28	57.187 mi
Registration #8	2023-09-28	57.187 mi
Registration #9	2023-09-28	57.187 mi

More info >



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20006104263 LN9