



report date: 2024-03-29

General information

Make	MINI
Model	MINI (R57) COOPER
Colour	Red
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-28
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-11-29
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	45
Total items failed	5

MOT #15	2021-11-04 11:28
MOT test number	433662352033
Result	✓ Passed
Next expiry date	2022-11-29
Advice	General under body surface and suspension rust
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2021-11-02 15:49
MOT test number	512542478725
Result	✗ Failed
MAJOR	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
DANGEROUS	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	General under body surface and suspension rust
MAJOR	Emissions not tested (8.2.1.2 (d))

MOT #13	2020-11-11 14:45
MOT test number	989546074516
Result	✓ Passed

**MOT #12** 2020-11-11 14:45**MOT test number** 238894701947**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**MOT #11** 2019-05-29 12:59**MOT test number** 322717924500**Result** ✓ Passed**MOT #10** 2019-05-22 14:14**MOT test number** 768205625195**Result** ✗ Failed**MAJOR** Exhaust emissions likely to be affected by an exhaust leak centre pipe split (8.2.2.1 (b))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2018-05-18 09:22**MOT test number** 812373460459**Result** ✓ Passed**Advice** Engine bay covers fitted obscuring various components**Advice** Engine management light on



MOT #8

2017-05-18 09:31

MOT test number

409077517936

Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)	
Advice	Oil level low	
Advice	Front Brake pad(s) wearing thin 70-80% worn (3.5.1g)	
Advice	Engine management light illuminated	
Advice	Play in steering rack inner joint(s)	
Advice	All tyres perished and cracking	
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	TPMS light illuminated	
Advice	Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)	

**MOT #7**

2017-05-17 09:17

MOT test number

916633567880

Result**✗ Failed****Fail**

Windscreen washer provides insufficient washer liquid (8.2.3)

Advice

Engine management light illuminated

Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice

All tyres perished and cracking

Advice

Exhaust has a minor leak of exhaust gases front flexy pipe (7.1.2)

Advice

Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Fail

Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Advice

Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Advice

TPMS light illuminated

Advice

Front Brake pad(s) wearing thin 70-80% worn (3.5.1g)

Advice

Oil level low

Advice

Play in steering rack inner joint(s)

MOT #6

2016-05-17 10:47

MOT test number

215801447602

Result**✓ Passed****Advice**

Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 29%. Limit 30% (3.7.B.5b)

Advice

Rear number plate quite loose

Advice

All tyres cracking, N/S/R 3mm

Advice

Rear brake disc worn, pitted or scored, but not seriously weakened Both (3.5.1i)

Advice

Front Exhaust has a minor leak of exhaust gases Flexi (7.1.2)

Advice

Oil and coolant levels low

**MOT #5** 2015-05-16 11:23**MOT test number** 948216435192**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Front wipers slightly split**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2014-05-24 15:12**MOT test number** 207514444421**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Rear brake discs lipped, pads visually ok**MOT #3** 2013-05-25 11:46**MOT test number** 349875543130**Result** ✓ Passed**MOT #2** 2013-05-25 11:46**MOT test number** 987945943138**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper blade insecure (8.2.2)**MOT #1** 2012-05-05 10:21**MOT test number** 929616522196**Result** ✓ Passed



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-05-29
Last registration	2021-11-04
Complete history	See info



Registration #1	2009-05-29	26 mi
Registration #2	2012-05-05	19.889 mi
Registration #3	2013-05-25	27.233 mi
Registration #4	2014-05-24	35.300 mi
Registration #5	2015-05-16	44.021 mi
Registration #6	2016-05-17	52.788 mi
Registration #7	2017-05-17	62.351 mi
Registration #8	2017-05-18	62.382 mi
Registration #9	2018-05-29	71.277 mi
Registration #10	2019-05-29	80.277 mi
Registration #11	2020-05-29	89.277 mi
Registration #12	2021-05-29	98.277 mi
Registration #13	2022-05-29	107.277 mi
Registration #14	2023-05-29	116.277 mi
Registration #15	2024-05-29	125.277 mi
Registration #16	2025-05-29	134.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1165 kg
Max. allowed weight	1595 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats 4

Engine number	B314I445
---------------	----------