



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVARO L1H1 2900 SPORTIVE CDTI BITURBO S/S
Colour	Silver
Year of manufacture	2017
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.1 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-05
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-17
MOT pass rate	50 %
MOT passed	5
Failed MOT tests	5
Total advice items	15
Total items failed	11

MOT #10	2024-03-14 14:59
MOT test number	829104746126
Result	✓ Passed
Next expiry date	2025-03-17
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2024-03-14 08:55
MOT test number	417446547439
Result	✗ Failed
Fail	Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Fail	Front Exhaust has a major leak of exhaust gases Exhaust and engine (6.1.2 (a))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Oil leaking excessively from engine (8.4.1 (a) (i))

MOT #8	2023-03-16 14:08
MOT test number	783291893134
Result	✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #7** 2023-03-15 11:04**MOT test number** 208746629398**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))**MOT #6** 2022-03-11 15:44**MOT test number** 976804851682**Result** ✓ Passed**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #5** 2022-03-11 15:12**MOT test number** 628461255360**Result** ✗ Failed**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both lamps (4.7.1 (b) (ii))**MOT #4** 2021-03-18 11:25**MOT test number** 597288314337**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #3** 2021-03-18 11:25**MOT test number** 172039777698**Result** ✗ Failed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #2** 2020-08-25 13:41**MOT test number** 590610977390**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2020-08-25 08:28**MOT test number** 323427981838**Result** ✗ Failed**Fail** Brake pad(s) less than 1.5 mm thick All front (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Brake pad(s) less than 1.5 mm thick All rear (1.1.13 (a) (ii))**Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
17 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	17 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VAUXH
Plate since	2024-03-29
Current registration	 VAUXH
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2017-09-13
Last registration	2024-03-14
Complete history	See info



Registration #1	2017-09-13	27 mi
Registration #2	2020-08-25	83.205 mi
Registration #3	2020-08-25	83.205 mi
Registration #4	2020-08-25	83.205 mi
Registration #5	2021-03-18	94.103 mi
Registration #6	2021-03-18	94.103 mi
Registration #7	2021-03-18	94.103 mi
Registration #8	2021-03-18	94.103 mi
Registration #9	2021-03-18	94.103 mi
Registration #10	2021-03-18	94.103 mi
Registration #11	2021-03-18	94.103 mi
Registration #12	2021-03-18	94.103 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	4498 mm
Kerb weight	1743 kg
Max. allowed weight	2980 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M D4 - C254856LQI