



report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Grey
Year of manufacture	2006
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-08-11
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)

Entry 1

Date	2021-08-10
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](http://autotrader.co.uk)



MOT history

MOT expiry date	2024-11-02
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	41
Total items failed	7

MOT #21	2023-11-03 16:14
MOT test number	821700851558
Result	✓ Passed
Next expiry date	2024-11-02
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing inner and outer edge (5.2.3 (d) (ii))
Advice	Brake pipe corroded, covered in grease or other material centre (1.1.11 (c))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Items removed from driver's view prior to test
Advice	Oil leak, but not excessive around sump (8.4.1 (a) (i))
Advice	Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #20**

2023-10-13 14:22

**MOT test number**

395827197803

**Result****✗ Failed**

- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- MAJOR** Windscreen washer not working (3.5 (a))
- MAJOR** Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- MAJOR** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))

**MOT #19**

2022-09-24 10:46

**MOT test number**

167821312212

**Result****✓ Passed**

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #18**

2022-09-24 10:46

**MOT test number**

611727606990

**Result****✗ Failed**

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Nearside Rear Stop lamp(s) not working bulb replaced (4.3.1 (a) (ii))

**MOT #17** 2021-10-02 09:24**MOT test number** 757727185045**Result** ✓ Passed**Minor** Offside Rear Rear fog lamp with a multiple light source up to 1/2 not functioning (4.5.1 (a) (i))**MOT #16** 2021-10-02 09:24**MOT test number** 114905214159**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp(s) not working bulb replaced (4.3.1 (a) (ii))**Minor** Offside Rear Rear fog lamp with a multiple light source up to 1/2 not functioning (4.5.1 (a) (i))**MOT #15** 2020-09-10 08:03**MOT test number** 122153651921**Result** ✓ Passed**MOT #14** 2019-10-04 08:09**MOT test number** 249629630214**Result** ✓ Passed**MOT #13** 2018-02-05 16:24**MOT test number** 958340299016**Result** ✓ Passed**MOT #12** 2017-02-03 13:36**MOT test number** 103370012218**Result** ✓ Passed

**MOT #11** 2016-01-27 09:40**MOT test number** 556186812943**Result** ✓ Passed**Advice** Brake pipes are greased**Advice** Both front tyres cracked & wearing on edges**MOT #10** 2015-01-21 09:41**MOT test number** 108511325051**Result** ✓ Passed**MOT #9** 2015-01-21 09:41**MOT test number** 549861425000**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #8** 2014-01-22 09:29**MOT test number** 188232024473**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #7** 2013-01-23 10:47**MOT test number** 165713123409**Result** ✓ Passed**Notice** Nearside front tyre worn to the legal limit & sidewall damaged**Notice** Nearside rear light unit condensated**Notice** Wipers poor**Notice** Screw in nearside rear tyre**MOT #6** 2012-02-02 14:44**MOT test number** 105733632093**Result** ✓ Passed**Notice** Nearside front tyre sidewall slight damage and on 3.5mm**Notice** Engine stabilizer starting to split**Notice** Offside rear tyre stepping on inner edge**MOT #5** 2012-02-02 09:35**MOT test number** 697023532001**Result** ✗ Failed**Notice** Offside rear tyre stepping on inner edge**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Nearside front tyre sidewall slight damage and on 3.5mm**Fail** Offside Front coil spring fractured (2.4.C.1a)**Notice** Engine stabilizer starting to split**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #4** 2011-02-02 09:30**MOT test number** 979993031022**Result** ✓ Passed**Notice** Minor chips in wind screen**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-02-08 10:52**MOT test number** 814369330085**Result** ✓ Passed**MOT #2** 2009-09-10 13:16**MOT test number** 384853359477**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-09-09 16:52**MOT test number** 151872559263**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
2 November 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	2 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-10-23
Last registration	2023-11-03
Complete history	<a href="#">See info</a>



Registration #1	2006-10-23	23 mi
Registration #2	2009-09-09	21.887 mi
Registration #3	2009-09-10	21.907 mi
Registration #4	2010-02-08	23.289 mi
Registration #5	2011-02-02	29.266 mi
Registration #6	2012-02-02	36.440 mi
Registration #7	2012-02-02	36.440 mi
Registration #8	2013-01-23	42.874 mi
Registration #9	2014-01-22	48.946 mi
Registration #10	2015-01-21	53.913 mi
Registration #11	2016-01-27	58.578 mi
Registration #12	2017-02-03	63.176 mi
Registration #13	2018-02-03	68.774 mi
Registration #14	2019-02-03	74.372 mi
Registration #15	2020-02-03	79.970 mi
Registration #16	2021-02-03	85.568 mi
Registration #17	2022-02-03	91.166 mi
Registration #18	2023-02-03	96.764 mi
Registration #19	2024-02-03	102.362 mi
Registration #20	2025-02-03	107.960 mi
Registration #21	2026-02-03	113.558 mi
Registration #22	2027-02-03	119.156 mi
Registration #23	2028-02-03	124.754 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	6L33722