




report date: 2024-03-28

General information

Make	VOLVO
Model	V70 S 140 V70
Colour	Green
Year of manufacture	2002
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	220 Nm at 3.750 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	39.8 mpg
Consumption combined	30.4 mpg
CO2 emission	229 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-09-13
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-19
MOT pass rate	68 %
MOT passed	19
Failed MOT tests	9
Total advice items	39
Total items failed	21

MOT #28 2023-09-19 11:14

MOT test number 860009426489

Result ✓ Passed

Next expiry date 2024-09-19

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #27 2022-09-20 11:12

MOT test number 842109366665

Result ✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Play in steering rack inner joint(s)

**MOT #26** 2021-09-14 16:34**MOT test number** 998794242327**Result** ✓ Passed**MOT #25** 2020-11-12 14:25**MOT test number** 192206139005**Result** ✓ Passed**MOT #24** 2019-11-21 11:48**MOT test number** 368151235057**Result** ✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #23 2018-11-29 12:13**MOT test number** 896627431080**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22 2017-12-07 15:56**MOT test number** 332853567071**Result** ✓ Passed



MOT #21	2016-11-25 10:38
MOT test number	688051640639
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Supplementary Restraint System warning lamp does not illuminate (5.4.2)

MOT #20	2016-11-25 10:38
MOT test number	707575968521
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)
Advice	Supplementary Restraint System warning lamp does not illuminate (5.4.2)
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)

MOT #19	2015-12-12 11:49
MOT test number	604306542815
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #18	2015-06-17 14:44
MOT test number	748788765138
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Play in steering rack inner joint(s)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #17** 2015-06-12 10:58**MOT test number** 567503965185**Result** ✗ Failed**Notice** Play in steering rack inner joint(s)**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #16** 2014-05-20 12:03**MOT test number** 287300344414**Result** ✓ Passed**MOT #15** 2013-06-12 11:28**MOT test number** 727873963145**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #14** 2013-06-12 11:28**MOT test number** 859123563183**Result** ✗ Failed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Pass with rectification** Fuel cap/sealing device sealing washer deteriorated (7.2.4c)**MOT #13** 2012-06-08 09:21**MOT test number** 736980062140**Result** ✓ Passed



MOT #12	2011-08-17 17:03
MOT test number	846449621264
Result	✓ Passed
Advice	Offside Tyre worn close to the legal limit (4.1.E.1)

MOT #11	2011-08-16 11:17
MOT test number	436048621264
Result	✗ Failed
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Offside rear parking brake recording little or no effort (3.7.B.6a)
Advice	Offside Tyre worn close to the legal limit (4.1.E.1)

MOT #10	2010-08-30 08:24
MOT test number	214622040207
Result	✓ Passed

MOT #9	2010-08-27 12:29
MOT test number	760149030208
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
Fail	Nearside Front constant velocity joint gaiter split (2.5.C.1a)

**MOT #8** 2009-09-01 12:05**MOT test number** 441834749220**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Centre Exhaust system not adequately supported (7.1.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2009-09-01 12:05**MOT test number** 554624549219**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2008-06-12 18:29**MOT test number** 682324068131**Result** ✓ Passed**MOT #5** 2008-06-11 18:18**MOT test number** 731213968176**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter split (2.5.C.1a)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**MOT #4** 2007-08-08 14:40**MOT test number** 284290627228**Result** ✓ Passed**MOT #3** 2007-08-08 11:19**MOT test number** 674960227267**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.5c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.5c)**MOT #2** 2006-08-07 15:19**MOT test number** 223949916261**Result** ✓ Passed**MOT #1** 2006-08-07 12:24**MOT test number** 333469716284**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
19 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	19 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2002-08-28
Last registration	2023-09-19
Complete history	See info



Registration #1	2002-08-28	21 mi
Registration #2	2006-08-07	22.429 mi
Registration #3	2006-08-07	22.429 mi
Registration #4	2007-08-08	26.166 mi
Registration #5	2007-08-08	26.171 mi
Registration #6	2008-06-11	29.577 mi
Registration #7	2008-06-12	29.589 mi
Registration #8	2009-09-01	39.718 mi
Registration #9	2010-08-27	47.515 mi
Registration #10	2010-08-30	47.515 mi
Registration #11	2011-08-16	54.516 mi
Registration #12	2011-08-17	54.517 mi
Registration #13	2012-06-08	61.274 mi
Registration #14	2013-06-12	64.999 mi
Registration #15	2013-06-12	64.999 mi
Registration #16	2013-06-12	64.999 mi
Registration #17	2013-06-12	64.999 mi
Registration #18	2013-06-12	64.999 mi
Registration #19	2013-06-12	64.999 mi
Registration #20	2013-06-12	64.999 mi
Registration #21	2013-06-12	64.999 mi
Registration #22	2013-06-12	64.999 mi
Registration #23	2013-06-12	64.999 mi
Registration #24	2013-06-12	64.999 mi
Registration #25	2013-06-12	64.999 mi
Registration #26	2013-06-12	64.999 mi

Registration #27	2025-05-20	25,000,000
Registration #28	2025-05-20	25,000,000

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1720 mm
Height	1400 mm
Length	4520 mm
Wheel base	2560 mm
Kerb weight	1483 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	2735519