



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	Black
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg





Internet history

Entry 1

Date	2021-12-10
Pictures	31
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #17	2022-12-28 15:02
MOT test number	530842326506
Result	✓ Passed
Next expiry date	2023-12-27
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Engin tray fitted

MOT #16	2021-12-02 13:34
MOT test number	270269452762
Result	✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing edges (5.2.3 (d) (ii))

MOT #15	2020-12-16 18:00
MOT test number	738809562505
Result	✓ Passed
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Front Oil leak, but not excessive engine (8.4.1 (a) (i))

MOT #14	2019-06-18 15:46
MOT test number	636108877385
Result	✓ Passed

MOT #13	2019-06-07 14:52
MOT test number	956077762720
Result	✗ Failed
Fail	Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))



MOT #12	2019-02-06 14:17
MOT test number	766528885865
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11	2019-02-06 13:01
MOT test number	561159336500
Result	✗ Failed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Headlamp light intensity severely reduced (4.1.4 (a))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Pass with rectification	Rear Registration plate does not conform to the specified requirements (0.1 (d))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2018-02-07 15:04
MOT test number	590208246466
Result	✓ Passed



MOT #9 2018-02-07 15:04

MOT test number 289094561776

Result ✗ Failed

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

MOT #8 2017-02-01 09:36

MOT test number 195974936614

Result ✓ Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7 2017-02-01 09:36

MOT test number 969827487316

Result ✗ Failed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2016-01-27 11:53

MOT test number 741320536689

Result ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #5 2016-01-27 11:53

MOT test number 625735771409

Result ✗ Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Rear Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #4 2015-02-06 17:04

MOT test number 526317335016

Result ✓ Passed

MOT #3 2015-02-06 17:04

MOT test number 359417335082

Result ✗ Failed

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #2 2014-02-06 09:50

MOT test number 699567934033

Result ✓ Passed

MOT #1 2013-02-09 11:58

MOT test number 136890443477

Result ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	BT59MBF
Plate since	2019-09-29
Current registration	BT59MBF
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-02-08
Last registration	2022-12-28
Complete history	See info



Registration #1	2010-02-08	23 mi
Registration #2	2013-02-09	24.622 mi
Registration #3	2014-02-06	31.329 mi
Registration #4	2015-02-06	43.430 mi
Registration #5	2016-01-27	53.906 mi
Registration #6	2016-01-27	53.906 mi
Registration #7	2017-02-01	68.019 mi
Registration #8	2017-02-01	68.019 mi
Registration #9	2018-02-07	78.857 mi
Registration #10	2019-02-07	89.700 mi
Registration #11	2019-02-07	89.700 mi
Registration #12	2019-02-07	89.700 mi
Registration #13	2019-02-07	89.700 mi
Registration #14	2019-02-07	89.700 mi
Registration #15	2019-02-07	89.700 mi
Registration #16	2019-02-07	89.700 mi
Registration #17	2019-02-07	89.700 mi
Registration #18	2019-02-07	89.700 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	957553