



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI GO
Colour	White
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	50.4 mpg
CO2 emission	147 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-26
Pictures	0
Listing price	<a href="#">View report</a>

source: heycar.co.uk



## MOT history

MOT expiry date	2024-11-05
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	14
Total items failed	9

MOT #11	2023-11-06 09:45
MOT test number	735895664588
Result	✓ Passed
Next expiry date	2024-11-05
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #10	2023-11-01 12:29
MOT test number	717844442104
Result	✗ Failed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Brake lever has insufficient reserve travel (1.1.2 (a))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #9	2022-11-04 10:45
MOT test number	379517878788
Result	✓ Passed

**MOT #8** 2022-10-31 13:12**MOT test number** 553548688611**Result** ✗ Failed**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**MOT #7** 2021-09-27 11:27**MOT test number** 443214695756**Result** ✓ Passed**Advice** Engine cover and under trays fitted obscuring view**MOT #6** 2020-10-12 17:17**MOT test number** 771136502538**Result** ✓ Passed**Advice** Oil leak, but not excessive sump region (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2020-10-12 09:21**MOT test number** 797757951751**Result** ✗ Failed**Advice** Oil leak, but not excessive sump region (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Brake relay lever has restricted free movement (1.1.15 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2019-10-02 09:36**MOT test number** 659998972321**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-10-16 10:20**MOT test number** 273112751216**Result** ✓ Passed**MOT #2** 2017-08-25 15:52**MOT test number** 893692019757**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2017-08-15 15:50**MOT test number** 802619645102**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)**Advice** Offside Rear Nail in tyre**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Nail in tyre



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
5 November 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	5 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-07-31
Last registration	2023-11-06
Complete history	<a href="#">See info</a>



Registration #1	2014-07-31	22 mi
Registration #2	2017-08-15	36.551 mi
Registration #3	2017-08-25	36.931 mi
Registration #4	2018-10-16	47.701 mi
Registration #5	2019-10-02	58.508 mi
Registration #6	2020-10-12	69.115 mi
Registration #7	2020-10-12	69.115 mi
Registration #8	2020-10-12	69.115 mi
Registration #9	2020-10-12	69.115 mi
Registration #10	2020-10-12	69.115 mi
Registration #11	2020-10-12	69.115 mi
Registration #12	2020-10-12	69.115 mi
Registration #13	2020-10-12	69.115 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

D4FDEZ280515