



Mercedes-Benz



report date: 2024-03-28

General information

|                     |                   |
|---------------------|-------------------|
| Make                | MERCEDES          |
| Model               | SLK 350           |
| Colour              | Silver            |
| Year of manufacture | 2005              |
| Top speed           | 155 mph           |
| 0 - 60 mph          | 5.5 seconds       |
| Gearbox             | 6 speed automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 268 BHP             |
| Max. torque             | 350 Nm at 5.000 rpm |
| Engine capacity         | 3.498 cc            |
| Cylinders               | 6                   |
| Fuel type               | Petrol              |
| Consumption city        | 19.9 mpg            |
| Consumption extra urban | 36.2 mpg            |
| Consumption combined    | 28.0 mpg            |
| CO2 emission            | 242 g/km            |
| CO2 label               | L                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-08-23                  |
| Pictures      | 12                          |
| Listing price | <a href="#">View report</a> |



source: cargurus.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-03-22 |
| MOT pass rate      | 88 %       |
| MOT passed         | 15         |
| Failed MOT tests   | 2          |
| Total advice items | 32         |
| Total items failed | 3          |

|                  |                  |
|------------------|------------------|
| MOT #17          | 2023-03-21 11:16 |
| MOT test number  | 787165119197     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-03-22       |

|                 |                  |
|-----------------|------------------|
| MOT #16         | 2022-03-23 10:10 |
| MOT test number | 257617267933     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #15         | 2021-10-19 13:59 |
| MOT test number | 371799065348     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #14         | 2021-10-19 13:59 |
| MOT test number | 228130091297     |
| Result          | ✗ Failed         |

**Pass with rectification** Rear Direction indicator incorrect colour both (4.4.3 (a))

**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

|                 |                  |
|-----------------|------------------|
| MOT #13         | 2021-01-27 13:00 |
| MOT test number | 505289311116     |
| Result          | ✓ Passed         |

**MOT #12** 2019-07-06 08:38**MOT test number** 890658880507**Result** ✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides on backs (1.1.14 (a) (ii))

**MOT #11** 2018-07-03 12:04**MOT test number** 875703703987**Result** ✓ Passed**MOT #10** 2017-08-10 10:34**MOT test number** 624097023216**Result** ✓ Passed**MOT #9** 2016-08-23 15:31**MOT test number** 200196445375**Result** ✓ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside front tyre wall damaged
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Engine cover and under tray fitted
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside and offside rear tyre walls damaged
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust system surface corrosion
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



|                 |  |
|-----------------|--|
| MOT #8          | 2016-08-23 12:24   |
| MOT test number | 496670469388   |
| Result          | ✗ Failed   |
| Advice          | Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)            |
| Advice          | Offside Rear Brake pad(s) wearing thin (3.5.1g)  |
| Advice          | Nearside and offside rear tyre walls damaged   |
| Advice          | Offside Rear Tyre worn close to the legal limit (4.1.E.1)                                    |
| Advice          | Exhaust system surface corrosion   |
| Fail            | Front Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a) |
| Advice          | Nearside Rear Brake pad(s) wearing thin (3.5.1g)   |
| Advice          | Nearside Rear Tyre worn close to the legal limit (4.1.E.1)                                   |
| Advice          | Nearside front tyre wall damaged   |
| Advice          | Engine cover and under tray fitted   |

|                 |   |
|-----------------|---|
| MOT #7          | 2015-05-26 11:14  |
| MOT test number | 249566345112  |
| Result          | ✓ Passed  |
| Advice          | Offside Rear Direction indicator slightly discoloured (1.4.A.2f)      |
| Advice          | Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)     |
| Notice          | Some tyre outer sidewall damage to both rear and nearside front tyres |

**MOT #6** 2014-04-29 16:31**MOT test number** 805809114181**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-04-30 10:53**MOT test number** 607060823167**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2012-12-22 10:36**MOT test number** 576117952384**Result** ✓ Passed**MOT #3** 2011-10-07 10:31**MOT test number** 407930681224**Result** ✓ Passed



|                 |                  |
|-----------------|------------------|
| MOT #2          | 2010-10-15 11:34 |
| MOT test number | 120628880290     |
| Result          | ✓ Passed         |
| MOT #1          | 2009-09-19 08:41 |
| MOT test number | 742472569226     |
| Result          | ✓ Passed         |



Tax & MOT check

✕  
Untaxed

Tax expired:  
1 April 2024

✕  
MOT

Expired:  
22 March 2024

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 1 April 2024         |
| Days left        | 28 days too late                |
| MOT expiry date  | 22 March 2024                   |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 48         |
| Band                                    | K          |
| Single payment (12 months)              | £ 395,00,- |
| Single six month payment                | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|                |            |
|----------------|------------|
| XXXXXXXXXX     | XXXXXXXXXX |
| XXXXXXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX     | XXXXXXXXXX |
| XXXXXX         | XXXXXXXXXX |
| XXXXXXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX     | XXXXXXXXXX |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

|                      |   |
|----------------------|---|
| Number of plates     | 1   |
| Current registration |  <b>XXXXXX</b> |
| Plate since          | 2020-01-01  |
| Current registration |  <b>XXXXXX</b> |
| Plate since          | 2020-01-01  |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 19                       |
| First mileage registration | 2005-10-29               |
| Last registration          | 2023-03-21               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2005-10-29 | 15 mi     |
| Registration #2  | 2009-09-19 | 33.409 mi |
| Registration #3  | 2010-10-15 | 39.579 mi |
| Registration #4  | 2011-10-07 | 42.183 mi |
| Registration #5  | 2012-12-22 | 47.568 mi |
| Registration #6  | 2013-04-30 | 48.582 mi |
| Registration #7  | 2014-04-29 | 60.348 mi |
| Registration #8  | 2015-05-26 | 67.622 mi |
| Registration #9  | 2016-08-23 | 67.755 mi |
| Registration #10 | 2016-08-23 | 67.755 mi |
| Registration #11 | 2016-08-23 | 67.755 mi |
| Registration #12 | 2016-08-23 | 67.755 mi |
| Registration #13 | 2016-08-23 | 67.755 mi |
| Registration #14 | 2016-08-23 | 67.755 mi |
| Registration #15 | 2016-08-23 | 67.755 mi |
| Registration #16 | 2016-08-23 | 67.755 mi |
| Registration #17 | 2016-08-23 | 67.755 mi |
| Registration #18 | 2016-08-23 | 67.755 mi |
| Registration #19 | 2016-08-23 | 67.755 mi |

More info >



Safety ratings

|             |                                 |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆                           |
| Video       | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1969 mm |
| Height              | 1296 mm |
| Length              | 4089 mm |
| Wheel base          | 2430 mm |
| Kerb weight         | 1390 kg |
| Max. allowed weight | 1780 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 70 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 2                     |
| Number of seats    | 2                     |
| Number of axles    | 2                     |
| Engine number      | 27296330118297        |