



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Grey
Year of manufacture	2012
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-30
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-11
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	27
Total items failed	14

MOT #14	2024-01-05 10:12
MOT test number	296730982011
Result	✓ Passed
Next expiry date	2025-01-11
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front wishbone bush (5.3.4 (a) (i))

MOT #13	2023-01-12 15:56
MOT test number	978886557261
Result	✓ Passed

MOT #12	2022-06-13 09:53
MOT test number	388400607321
Result	✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11	2021-07-06 10:20
MOT test number	181180320156
Result	✓ Passed

**MOT #10** 2021-05-27 13:36**MOT test number** 888693458063**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MOT #9** 2021-05-27 11:07**MOT test number** 870785738979**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside wiper blade smearing windscreen slightly**MOT #8** 2020-07-02 14:58**MOT test number** 159207511319**Result** ✓ Passed

**MOT #7** 2020-07-02 09:32**MOT test number** 434019060021**Result** ✗ Failed

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Nearside Front Service brake excessively binding (1.2.1 (f))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Reversing lamp inoperative (4.6.1 (a))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))

MOT #6 2020-03-20 17:25**MOT test number** 843893556939**Result** ✗ Failed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Rear Reversing lamp inoperative (4.6.1 (a))

**MOT #5**

2019-03-28 16:30

MOT test number

596586706581

Result

✓ Passed

Advice Oil leak, but not excessive Sump area (8.4.1 (a) (i))**Advice** Rear wiper smears screen**MOT #4**

2019-03-28 12:11

MOT test number

140251123672

Result

✗ Failed

Fail Nearside Front Headlamp aim too low (4.1.2 (a))**Fail** Nearside Rear Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))**Advice** Rear wiper smears screen**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Advice** Oil leak, but not excessive Sump area (8.4.1 (a) (i))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #3**

2017-10-31 14:06

MOT test number

358502773257

Result

✓ Passed

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)



MOT #2	2016-11-04 16:48
MOT test number	761153936364
Result	✓ Passed
Advice	Offside Rear tyre wearing on edge
Advice	Front slight bind on front brakes

MOT #1	2015-11-16 00:00
MOT test number	809940624514
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
11 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 PHZ3561
Plate since	2024-03-28
Current registration	 PHZ3561
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-09-07
Last registration	2024-01-05
Complete history	See info



Registration #1	2012-09-07	13 mi
Registration #2	2015-11-16	13.948 mi
Registration #3	2016-11-04	23.286 mi
Registration #4	2017-10-31	30.772 mi
Registration #5	2019-03-28	41.860 mi
Registration #6	2019-03-28	41.860 mi
Registration #7	2020-03-20	47.907 mi
Registration #8	2020-07-02	47.916 mi
Registration #9	2020-07-02	47.916 mi
Registration #10	2020-07-02	47.916 mi
Registration #11	2020-07-02	47.916 mi
Registration #12	2020-07-02	47.916 mi
Registration #13	2020-07-02	47.916 mi
Registration #14	2020-07-02	47.916 mi
Registration #15	2020-07-02	47.916 mi
Registration #16	2020-07-02	47.916 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	172361K