



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Silver
Year of manufacture	2005
Top speed	113 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	169 Nm at 2.400 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.1 mpg
Consumption extra urban	38.7 mpg
Consumption combined	29.4 mpg
CO2 emission	226 g/km
CO2 label	L







Internet history

Entry 1

Date	2021-05-25
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-29
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	40
Total items failed	4

MOT #21	2024-03-20 13:36
MOT test number	618848424166
Result	✓ Passed
Next expiry date	2025-03-29

MOT #20	2023-03-15 14:51
MOT test number	413303412571
Result	✓ Passed

MOT #19	2022-03-23 10:54
MOT test number	608436584631
Result	✓ Passed

MOT #18	2021-03-25 12:01
MOT test number	630600203017
Result	✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on both edges (5.2.3 (e))
- Advice** Engine covers fitted
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on both edges (5.2.3 (e))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

**MOT #17**

2021-03-25 10:32

MOT test number

792702375424

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on both edges (5.2.3 (e))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on both edges (5.2.3 (e))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Engine covers fitted

MOT #16

2020-03-16 13:51

MOT test number

156089411065

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside and offside front suspension top mounts have play in the upper attachments
- Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Engine covers fitted
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))

**MOT #15**

2020-03-16 10:53

MOT test number

932769902481

Result**✗ Failed**

- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn outer (5.3.4 (a) (i))
- Advice** Nearside and offside front suspension top mounts have play in the upper attachments
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Engine covers fitted
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2019-03-20 08:45

MOT test number

947662376190

Result**✓ Passed**

- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #13

2019-03-15 10:00

MOT test number

145924883114

Result**✗ Failed**

- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #12** 2018-03-09 13:50**MOT test number** 321274761038**Result** ✓ Passed**MOT #11** 2017-03-02 12:18**MOT test number** 660613772855**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**MOT #10** 2016-03-30 13:35**MOT test number** 896184430746**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 3mm, smooth inner shoulder Recommend replace (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 3mm, smooth inner shoulder Recommend replace (4.1.E.1)**MOT #9** 2015-03-17 12:58**MOT test number** 125806375078**Result** ✓ Passed**MOT #8** 2014-03-18 16:22**MOT test number** 335817774005**Result** ✓ Passed**Notice** Offside rear tyre heavily perishing.**Notice** Nearside rear tyre slight perishing.**MOT #7** 2013-03-26 07:50**MOT test number** 429445883069**Result** ✓ Passed

**MOT #6** 2012-07-18 16:22**MOT test number** 356140402412**Result** ✓ Passed**MOT #5** 2011-08-08 09:51**MOT test number** 125560021231**Result** ✓ Passed**Notice** Front discs light corrosion/worn**MOT #4** 2011-08-08 09:51**MOT test number** 146070821287**Result** ✗ Failed**Notice** Front discs light corrosion/worn**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #3** 2010-10-12 12:52**MOT test number** 120875480243**Result** ✓ Passed**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #2** 2009-09-29 11:11**MOT test number** 103082779212**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2008-08-27 08:44**MOT test number** 794210048243**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
29 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	29 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-07-25
Last registration	2024-03-20
Complete history	See info



Registration #1	2005-07-25	28 mi
Registration #2	2008-08-27	22.186 mi
Registration #3	2009-09-29	26.966 mi
Registration #4	2010-10-12	31.923 mi
Registration #5	2011-08-08	36.039 mi
Registration #6	2012-07-18	39.466 mi
Registration #7	2013-03-26	41.362 mi
Registration #8	2014-03-18	43.479 mi
Registration #9	2015-03-17	45.739 mi
Registration #10	2016-03-30	49.233 mi
Registration #11	2017-03-02	52.159 mi
Registration #12	2018-03-20	55.277 mi
Registration #13	2019-03-20	58.277 mi
Registration #14	2020-03-20	61.277 mi
Registration #15	2021-03-20	64.277 mi
Registration #16	2022-03-20	67.277 mi
Registration #17	2023-03-20	70.277 mi
Registration #18	2024-03-20	73.277 mi
Registration #19	2025-03-20	76.277 mi
Registration #20	2026-03-20	79.277 mi
Registration #21	2027-03-20	82.277 mi
Registration #22	2028-03-20	85.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1359 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	AZJ739712