



FV09NVK

report date: 2024-03-29

General information

Make	MAZDA
Model	3 D SPORT
Colour	Blue
Year of manufacture	2009
Top speed	132 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 1.800 rpm
Engine capacity	2.183 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F





MOT history

MOT expiry date	2021-12-16
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	13
Total items failed	10

MOT #14 2020-12-17 16:41

MOT test number 433368325634

Result ✓ Passed

Next expiry date 2021-12-16

Advice Suspension arm pin or bush worn but not resulting in excessive movement all rear (5.3.4 (a) (i))

Advice Coil spring corroded both rear (5.3.1 (b) (i))

MOT #13 2020-12-12 11:56

MOT test number 914961497422

Result ✗ Failed

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Suspension arm pin or bush worn but not resulting in excessive movement all rear (5.3.4 (a) (i))

Fail Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))

Advice Coil spring corroded both rear (5.3.1 (b) (i))

MOT #12 2019-05-23 13:35

MOT test number 211034358627

Result ✓ Passed

**MOT #11** 2019-05-22 16:22**MOT test number** 633508808555**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Central Front under engine guard loose**MOT #10** 2018-06-18 10:56**MOT test number** 106839029433**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2017-06-14 11:22**MOT test number** 561373164691**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #8** 2016-06-16 14:02**MOT test number** 850100593010**Result** ✓ Passed

**MOT #7** 2016-06-15 09:26**MOT test number** 369701358679**Result** ✗ Failed**Fail** Driver's seat insecure (6.2.A.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #6** 2015-06-17 16:07**MOT test number** 229938165481**Result** ✓ Passed**MOT #5** 2015-06-17 12:04**MOT test number** 158158765154**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #4** 2014-06-18 14:15**MOT test number** 189299364139**Result** ✓ Passed**MOT #3** 2013-05-18 13:33**MOT test number** 866688933193**Result** ✓ Passed



MOT #2	2013-05-16 15:35
MOT test number	989826833154
Result	✗ Failed
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #1	2012-06-19 14:50
MOT test number	825281872157
Result	✓ Passed
Notice	O/s rear tyre has low tread on inner edge
Notice	Nail in nearside rear tyre



Tax & MOT check

✕
Untaxed

Tax expired:
11 January 2021

✕
MOT

Expired:
16 December 2021

Tax status	Expired at 11 January 2021
Days left	1205 days too late
MOT expiry date	16 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-08-14
Last registration	2020-12-17
Complete history	See info



Registration #1	2009-08-14	12 mi
Registration #2	2012-06-19	39.873 mi
Registration #3	2013-05-16	53.776 mi
Registration #4	2013-05-18	53.776 mi
Registration #5	2014-06-18	64.087 mi
Registration #6	2015-06-17	77.174 mi
Registration #7	2015-06-17	77.174 mi
Registration #8	2016-06-15	88.870 mi
Registration #9	2016-06-15	88.870 mi
Registration #10	2016-06-15	88.870 mi
Registration #11	2016-06-15	88.870 mi
Registration #12	2016-06-15	88.870 mi
Registration #13	2016-06-15	88.870 mi
Registration #14	2016-06-15	88.870 mi
Registration #15	2016-06-15	88.870 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4490 mm
Wheel base	2640 mm
Kerb weight	1450 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10225780