





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE
Colour	Black
Year of manufacture	2015
Top speed	100 mph
0 - 100 km/h	14.3 seconds
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	44 kW / 60 HP / 59 BHP
Max. torque	95 Nm at 3.000 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/12



SD65OLB report date: 2024-03-28

Internet history

Entry 1

Date	2021-08-31	
Pictures	1	
Listing price	<u>View report</u>	



source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2023-09-29
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	25
Total items failed	2

MOT #8		2022-09-30 15:22
MOT test	number	909757861811
Result		✓ Passed
Next expi	ry date	2023-09-29
Advice	Under-trays fitted obscuring the view of some components	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Central Items removed from driver's view prior to test	
Advice (5.3.4 (a)	Offside Front Suspension arm pin or bush worn but not resulting in excess(i))	sive movement rear bush
Advice	Handbrake lever has long travel - repair or adjustment required.	

CarCheck.co.uk page 3/12



Pass with rectification

SD65OLB

report date: 2024-03-28

MOT #7 2022-09-30 15:22 629745334470 **MOT** test number Result × Failed **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i)) Pass with rectification Nearside Headlamp aim too high (4.1.2 (a)) **Advice** Handbrake lever has long travel - repair or adjustment required. Advice Central Items removed from driver's view prior to test Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f)) Advice Under-trays fitted obscuring the view of some components

MOT #6

MOT test number

815970559263

Result

✓ Passed

Offside Headlamp aim too high (4.1.2 (a))

MOT #5

MOT test number

260471407535

Result

✓ Passed

Minor

Rear Windscreen wiper blade defective (3.4 (b) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4 2020-09-07 09:42

MOT test number 465900959254

Result X Failed

MAJOR Brake lever has insufficient reserve travel (1.1.2 (a))

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Nearside Rear Service brake excessively binding (1.2.1 (f))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Rear Windscreen wiper blade defective (3.4 (b) (i))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

DANGEROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #3 2019-09-30 12:46

MOT test number 549347902115

Result \(\sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2019-09-30 10:29

MOT test number 495824455309

Result X Failed

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2018-09-19 08:24

MOT test number 475958281207

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check





Expired: 29 September 2023

Tax status	Valid until 1 September
Days left	126
MOT expiry date	29 September 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-24
Last registration	2022-09-30
Complete history	See info



Registration #1	2015-09-24	22 mi
Registration #2	2018-09-19	34.594 mi
Registration #3	2019-09-30	40.761 mi
Registration #4	2019-09-30	40.761 mi
Registration #5	2020-09-07	45.137 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea
		1.77 m
Registration #7		11.77 es 11.77 es 11.77 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditionir
50295	
60482	
60501	
60566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1453 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
CarChaeleeaule	nama 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CHYA451626