






report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER TD HARD TOP
Colour	Red
Year of manufacture	2010
Top speed	82 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel
Consumption city	22.6 mpg
Consumption extra urban	32.8 mpg
Consumption combined	28.3 mpg



CarCheck.co.uk page 1/14



Internet history

Entry 1


Date 2021-12-22

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2023-12-07
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	36
Total items failed	10

MOT #16		2022-12-08 11:32
MOT test	number	907354725253
Result		✓ Passed
Next expi	ry date	2023-12-07
Advice	Rear Lower Shock absorbers has a slightly worn bush Both. (5.3.2 (c))	
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Advice Front Seat belt webbing slightly damaged or frayed Both. (7.1.2 (b) (ii))	
Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush. (5.3.4 (a) (i))		
Advice	Oil leak, but not excessive Transfer box. (8.4.1 (a) (i))	
Advice (c))	Front Brake pipe corroded, covered in grease or other material Both covered	in grease. (1.1.11

MOT #15		2021-11-26 11:50
MOT test	number	579601270256
Result		✓ Passed
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Rear Lower Shock absorbers has a slightly worn bush Both sides (5.3.2 (c))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/14



MOT #14

MOT test number

Result

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #13

MOT test number

534600370954

Result

MAJOR Front Windscreen wiper blade missing (3.4 (b) (ii))

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MAJOR Rear Shock absorbers has an excessively worn bush Both sides upper and lower (5.3.2 (c))

MAJOR Steering box has excessive free play detected at the steering wheel (steering box fitted) (2.3 (a) (i))

MOT #12		2019-12-06 09:45
MOT test	number	713285800765
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Upper Shock absorbers has a slightly worn bush Both sides (5.3.2 (c))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Rear Lower Shock absorbers has a slightly worn bush Both sides (5.3.2 (c))	

CarCheck.co.uk page 4/14



Advice

DANGEROUS

Oil leak, but not excessive (8.4.1 (a) (i))

CN60JVL report date: 2024-03-28

MOT test number

Result

MAJOR Nearside Windscreen wiper not working (3.4 (a))

Advice Rear Upper Shock absorbers has a slightly worn bush Both sides (5.3.2 (c))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Rear Lower Shock absorbers has a slightly worn bush Both sides (5.3.2 (c))

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT test number

Result

Advice
Oil leak

Rear Lower Shock absorber has a slightly worn bush Both (2.7.4)

CarCheck.co.uk page 5/14



MOT #8

MOT test number

491668723666

Result

Advice Oil leak

Pass with rectification Nearside Front Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Advice Rear Lower Shock absorber has a slightly worn bush Both (2.7.4)

Pass with rectification Offside Rear Rear position lamp(s) not working (1.1.A.3b)

MOT #7

MOT test number

898475082830

Result

Advice Oil leak

MOT test number

Result

Advice Oil leak

Pass with rectification

Nearside Registration plate lamp not working (1.1.C.1d)

Pass with rectification

Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #5

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

2016-01-05 17:31

224110567875

✓ Passed

CarCheck.co.uk page 6/14



Result

Result

CN60JVL report date: 2024-03-28

✓ Passed

X Failed

MOT #4 2014-12-01 11:24

MOT test number 295725034355

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #3 2014-12-01 11:24

MOT test number 826315634303

Pass with rectification Offside Rear Direction indicator not working (1.4.A.2c)

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2013-12-13 10:47

MOT test number 839877043362

Result ✓ Passed

MOT #1 2013-11-04 10:32

MOT test number 286328103371

Result X Failed

Fail Offside Headlamp aim too low (1.8)

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Nearside Headlamp aim beam image kick up to the offside (1.8)

CarCheck.co.uk page 7/14



Tax & MOT check



X MOT

Expired: 7 December 2023

Tax status Expired at 1 March 2024

Days left 58 days too late

MOT expiry date 7 December 2023

Full MOT history See MOT history

CarCheck.co.uk page 8/14




Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	
Туре	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download to	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-10-29
Last registration	2022-12-08
Complete history	See info



Registration #1	2010-10-29	22 mi
Registration #2	2013-11-04	35.855 mi
Registration #3	2013-12-13	35.880 mi
Registration #4	2014-12-01	47.807 mi
Registration #5	2016-01-05	60.628 mi
Registration #6	2017-01-03	73.482 mi
Registration #7	2017-01-03	73.482 mi
Registration #8	2018-01-03	83.392 mi
Registration #9	2018-01-03	83.392 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		70,777 es

More info >

CarCheck.co.uk page 13/14



Dimensions & weight

Width	1790 mm
Height	2128 mm
Length	4040 mm
Kerb weight	1759 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	100713031244244DT

CarCheck.co.uk page 14/14