



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 D-4D XT3
Colour	Silver
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	173 g/km
CO2 label	H





MOT history

MOT expiry date	2020-12-19
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	30
Total items failed	18

MOT #16	2020-12-15 10:02
---------	------------------

MOT test number	808790003874
-----------------	--------------

Result	✗ Failed
<div>Minor</div> Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
<div>Fail</div> Offside Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))	
<div>Advice</div> Rear suspension corroded	
<div>Fail</div> Nearside Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))	



MOT #152019-12-20 15:24

MOT test number816362905626

Result✓ Passed

- Advice** Surface rust on rear subframe
- Advice** Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front headlamp in poor condition/ misted
- Advice** Towbar rusty
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Parking brake needs adjustment lever towards end of travel
- Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Nail in tyre
- Advice** N/s/f arch guard missing

**MOT #14**

2019-11-01 11:43

MOT test number

259061595150

Result**✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))
- Advice** N/s/f wheel arch guard missing
- Fail** Offside Front Suspension arm pin or bush likely to become detached rear bush (5.3.4 (a) (ii))
- Fail** Central Prop shaft bearing excessively worn (6.1.7 (b) (i))
- Advice** Rear suspension rusty
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Front Electrical wiring likely to touch hot or rotating parts (4.11 (a) (iii))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Front bumper damaged and cracked
- Fail** Offside Front Side repeater likely to become detached (4.4.1 (c) (ii))
- Advice** Rear diff mounting breaking up
- Fail** Offside Front Undertray likely to become detached (6.2.1 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #13** 2018-11-02 10:37**MOT test number** 799106036706**Result** ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12 2017-11-03 12:28**MOT test number** 890692973128**Result** ✓ Passed**MOT #11** 2017-10-24 15:10**MOT test number** 474434175111**Result** ✗ Failed

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #10 2016-10-18 09:30**MOT test number** 707036901546**Result** ✓ Passed**MOT #9** 2016-10-18 09:30**MOT test number** 753307487862**Result** ✗ Failed

Pass with rectification Offside Headlamp aim too high (1.8)

Pass with rectification Nearside Headlamp aim too high (1.8)

**MOT #8** 2015-08-26 15:56**MOT test number** 583180107713**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly corroded to rear (3.6.B.2c)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Brake pipe slightly corroded to rear (3.6.B.2c)**MOT #7** 2014-08-27 11:00**MOT test number** 439819234205**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-07-16 16:10**MOT test number** 358427893153**Result** ✓ Passed**MOT #5** 2012-07-18 14:23**MOT test number** 145180802249**Result** ✓ Passed**MOT #4** 2011-07-26 15:18**MOT test number** 275647301281**Result** ✓ Passed



MOT #3	2011-07-26 15:18
MOT test number	976817001256
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2	2010-07-22 16:33
MOT test number	283723600234
Result	✓ Passed

MOT #1	2009-08-20 15:09
MOT test number	302242639276
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 March 2021

✕
MOT

Expired:
19 December 2020

Tax status	Expired at 1 March 2021
Days left	1155 days too late
MOT expiry date	19 December 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-08-31
Last registration	2020-12-15
Complete history	See info



Registration #1	2006-08-31	16 mi
Registration #2	2009-08-20	20.112 mi
Registration #3	2010-07-22	26.982 mi
Registration #4	2011-07-26	32.924 mi
Registration #5	2012-07-18	38.595 mi
Registration #6	2013-07-16	45.000 mi
Registration #7	2014-08-27	54.514 mi
Registration #8	2015-08-26	62.920 mi
Registration #9	2016-08-26	71.326 mi
Registration #10	2017-08-26	79.732 mi
Registration #11	2018-08-26	88.138 mi
Registration #12	2019-08-26	96.544 mi
Registration #13	2020-08-26	104.950 mi
Registration #14	2021-08-26	113.356 mi
Registration #15	2022-08-26	121.762 mi
Registration #16	2023-08-26	130.168 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1585 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2AD0082158