




report date: 2024-03-29

## General information

Make	VOLVO
Model	V70 SE LUX
Colour	Grey
Year of manufacture	2008
Top speed	146 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	238 BHP
Max. torque	320 Nm at 3.200 rpm
Engine capacity	3.192 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.3 mpg
Consumption extra urban	36.7 mpg
Consumption combined	26.9 mpg
CO2 emission	251 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-12-24
Pictures	32
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-25
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	29
Total items failed	2

MOT #14	2023-10-02 10:35
MOT test number	391507784769
Result	✓ Passed
Next expiry date	2024-10-25
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))
Advice	Exhaust mounting defective (6.1.2 (a))

MOT #13	2022-10-04 12:59
MOT test number	413395913411
Result	✓ Passed

**MOT #12**

2021-10-26 15:53

**MOT test number**

305217029054

**Result**

✓ Passed

- Advice** Nearside Front Exhaust mounting defective (6.1.2 (a))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement o/s and n/s both bushs (5.3.4 (a) (i))
- Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge wearing thin (5.2.3 (e))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge wearing thin (5.2.3 (e))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Rear Upper Shock absorbers has a slightly worn bush o/s and n/s (5.3.2 (c))
- Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge close to markers and thin outer (5.2.3 (e))

**MOT #11**

2020-09-21 08:55

**MOT test number**

873165707042

**Result**

✓ Passed

- Advice** Rear exhaust mount bracket corroded and broke away
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge fdeathered inner and perished outer (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #10** 2019-09-25 09:30**MOT test number** 122364720447**Result** ✓ Passed**Advice** Suspension arm pin or bush worn but not resulting in excessive movement Both rear trailing arm bushes (5.3.4 (a) (i))**Advice** Offside Rear Nail in tyre**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2019-09-25 09:30**MOT test number** 385950054221**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Side repeater not working (4.4.1 (a) (ii))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement Both rear trailing arm bushes (5.3.4 (a) (i))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear Nail in tyre**MOT #8** 2018-11-05 14:53**MOT test number** 945162203697**Result** ✓ Passed**Advice** 2/ slight uneven tread wear on o/s rear tyre**Advice** 1/ unable to check outer sills fully due to sill covers**MOT #7** 2017-11-03 14:15**MOT test number** 300406804148**Result** ✓ Passed

**MOT #6** 2016-10-07 12:17**MOT test number** 900207368597**Result** ✓ Passed**MOT #5** 2015-10-24 09:37**MOT test number** 730270636619**Result** ✓ Passed**Advice** Rear brake pads getting low**Advice** Under engine covers fitted obscuring some steering/suspension items**Advice** Offside Rear Tyre has a cut ,but not to cords and bald inner edge**MOT #4** 2014-10-25 09:25**MOT test number** 278168094230**Result** ✓ Passed**MOT #3** 2013-10-31 11:18**MOT test number** 308054303303**Result** ✓ Passed**MOT #2** 2012-11-24 09:31**MOT test number** 409949022371**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2011-12-13 17:34**MOT test number** 685457241370**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
25 October 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	25 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-06-24
Last registration	2023-10-02
Complete history	<a href="#">See info</a>



Registration #1	2008-06-24	25 mi
Registration #2	2011-12-13	40.190 mi
Registration #3	2012-11-24	48.804 mi
Registration #4	2013-10-31	56.888 mi
Registration #5	2014-10-25	66.258 mi
Registration #6	2015-10-24	75.999 mi
Registration #7	2016-10-07	84.196 mi
Registration #8	2017-11-03	97.931 mi
Registration #9	2018-10-25	107.217 mi
Registration #10	2019-10-25	116.503 mi
Registration #11	2020-10-25	125.789 mi
Registration #12	2021-10-25	135.075 mi
Registration #13	2022-10-25	144.361 mi
Registration #14	2023-10-02	153.647 mi
Registration #15	2023-10-02	162.933 mi
Registration #16	2023-10-02	172.219 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1786 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	25060714330