



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI T3
Colour	Blue
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 2

Date	2022-01-09
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2022-01-07
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-27
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	44
Total items failed	9

MOT #19 2023-08-16 13:58

MOT test number 652582946241

Result ✓ Passed

Next expiry date 2024-08-27

Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Minor Front Windscreen wiper blade defective both (3.4 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #18 2023-08-15 16:07

MOT test number 511821658603

Result ✗ Failed

Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Minor Front Windscreen wiper blade defective both (3.4 (b) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Fail Rear fog lamp lens defective such that emitted light is adversely affected complete OSR lamp unit. white light showing when fog light is on (4.5.1 (b) (ii))

**MOT #17**

2022-08-23 12:07

MOT test number

893021439757

Result

✓ Passed

Advice

Rear Coil spring corroded (5.3.1 (b) (i))

MOT #16

2021-08-24 14:50

MOT test number

602625950465

Result

✓ Passed

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15

2020-08-28 10:32

MOT test number

961034327825

Result

✓ Passed

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Rear Nail in tyre

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14

2020-08-28 10:32

MOT test number

204687634220

Result

✗ Failed

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification

Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice

Offside Rear Nail in tyre

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2019-08-12 08:50**MOT test number** 411191593378**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-08-06 09:06**MOT test number** 277650724057**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #11** 2018-08-06 09:06**MOT test number** 929660999441**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #10** 2017-08-10 11:04**MOT test number** 519515439369**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2016-08-09 15:19**MOT test number** 317907928853**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt x 2**MOT #8** 2015-07-21 14:23**MOT test number** 686342005277**Result** ✓ Passed**MOT #7** 2015-07-21 11:36**MOT test number** 137482705289**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.2a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2014-08-04 10:12**MOT test number** 958266414258**Result** ✓ Passed**Advice** Front Brake lining(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2013-08-06 12:32**MOT test number** 616978213252**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2012-08-02 11:58**MOT test number** 508785512292**Result** ✓ Passed**Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Notice** Rear n/s brake pad 85% worn**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Baby seat fitted**MOT #3** 2012-07-31 10:17**MOT test number** 145653212210**Result** ✗ Failed**Notice** Baby seat fitted**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear n/s brake pad 85% worn**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)



MOT #2	2011-06-11 11:55
MOT test number	177992461185
Result	✓ Passed
<div>Notice Child seat fitted not allowing full inspection of adult belt</div>	

MOT #1	2010-06-07 17:18
MOT test number	953288350171
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
27 August 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	27 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-10
Last registration	2023-08-16
Complete history	See info



Registration #1	2007-03-10	27 mi
Registration #2	2010-06-07	35.750 mi
Registration #3	2011-06-11	40.139 mi
Registration #4	2012-07-31	45.947 mi
Registration #5	2012-08-02	45.979 mi
Registration #6	2013-08-06	50.389 mi
Registration #7	2014-08-04	55.043 mi
Registration #8	2015-07-21	59.328 mi
Registration #9	2015-07-21	59.328 mi
Registration #10	2016-08-09	64.189 mi
Registration #11	2017-08-10	69.312 mi
Registration #12	2018-08-10	74.435 mi
Registration #13	2019-08-10	79.558 mi
Registration #14	2020-08-10	84.681 mi
Registration #15	2021-08-10	89.804 mi
Registration #16	2022-08-10	94.927 mi
Registration #17	2023-08-16	100.050 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		
Registration #22		

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1470 mm
Length	4410 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	3ZZU883553