






report date: 2024-03-29

General information

Make	FORD
Model	MONDEO TITANIUM TDCI
Colour	Grey
Year of manufacture	2007
Top speed	129 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	329 Nm at 1.800 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date	2021-06-09
Pictures	2
Listing price	View report





source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-03-15
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	36
Total items failed	4

MOT #21		2024-03-16 14:08
MOT test	number	396050190971
Result		✓ Passed
Next expi	ry date	2025-03-15
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #20		2023-02-21 16:00
MOT test	number	151456985273
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/14



Result

KG07ZKI report date: 2024-03-29

MOT #19 2022-02-15 15:44

MOT test number 301555916553

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Nearside Front Drag link end ball joint dust cover damaged or deteriorated, but preventing the Minor ingress of dirt (2.1.3 (g) (i))

MOT #18 2021-02-15 18:19

903451412515 **MOT** test number

✓ Passed

Advice Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Anti-roll bar linkage ball joint has slight play offside rear and nearside rear (5.3.4 (a) (i))

MOT #17 2021-02-15 15:18

MOT test number 226271079763

Result × Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Nearside Rear Service brake excessively binding (1.2.1 (f)) **MAJOR**

Anti-roll bar linkage ball joint has slight play offside rear and nearside rear (5.3.4 (a) (i)) Advice

Advice Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **DANGEROUS**

MAIOR Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))

CarCheck.co.uk page 4/14



MOT #16 2020-02-19 16:22

MOT test number 593461447650

Result \rightarrow Passed

Advice Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))

MOT #15 2020-02-19 15:09

MOT test number 247259737097

Result X Failed

Advice Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Nearside Rear Service brake excessively binding (1.2.1 (f))

MOT #14 2019-02-04 14:59

MOT test number 998532085887

Result

Passed

Advice Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))

MOT #13 2019-02-04 11:15

MOT test number 411270039025

Result × Failed

MAJOR Nearside Front Position lamp not working (4.2.1 (a))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))

MAJOR Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))

CarCheck.co.uk page 5/14



MOT #12

KG07ZKJ report date: 2024-03-29

2018-02-22 16:12

MOT test number 627923968505

MOT #11 2017-02-20 11:12

MOT test number 109237840956

Result

Passed

Advice Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #10 2016-02-22 15:15

MOT test number 874203507114

Advice Brake pipe slightly corroded all pipes (3.6.B.2c)

MOT #9 2016-02-22 09:15

MOT test number 922285585879

Result X Failed

Advice Brake pipe slightly corroded all pipes (3.6.B.2c)

Fail Offside Front coil spring broken (2.4.C.1a)

MOT #8 2015-02-20 09:13

MOT test number 328301255001

MOT #7 2015-02-13 10:09

MOT test number 157934245080

Result × Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/14



MOT #6 2014-02-13 15:01

MOT test number 387824744045

Result Passed

Notice Nsr tyre worn in places to 2mm

MOT #5 2013-02-14 14:06

MOT test number 166685943026

Result ✓ Passed

MOT #4 2012-02-13 14:57

MOT test number 198044442026

Notice Front brake discs worn

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #3 2011-02-10 10:18

MOT test number 455521241065

Result \rightarrow Passed

MOT #2 2011-02-08 10:00

MOT test number 629149631036

Result × Failed

Fail Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2010-02-04 09:42

MOT test number 902515430034

Result
✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
manage of the same	

THE PARTY OF THE P	

	Managinga X
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of states	
Current registration	NK NE
Plate since	
Correct registration	UK UK
	UK
Plate since	
	Mara info
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-04-12
Last registration	2024-03-16
Complete history	See info



Registration #1	2007-04-12	19 mi
Registration #2	2010-02-04	24.989 mi
Registration #3	2011-02-08	33.235 mi
Registration #4	2011-02-10	33.351 mi
Registration #5	2012-02-13	41.107 mi
Registration #6	2013-02-14	49.519 mi
Registration #7	2014-02-13	57.349 mi
Registration #8	2015-02-13	65.762 mi
Registration #9	2015-02-20	65.813 mi
Registration #10	2016-02-22	73.981 mi
Registration #11	2016-02-22	73.981 mi
Registration #12	2017-02-20	79.939 mi
-		
Registration #13		77,777 esi
		11.77 m
Registration #13		11.777 es 11.777 es
Registration #13 Registration #14		11.77 m
Registration #13 Registration #14 Registration #15		11.77 mi 11.77 mi 11.77 mi 11.77 mi
Registration #13 Registration #14 Registration #15 Registration #16		11.77 es 11.77 es 11.77 es 11.77 es
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1958 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Kerb weight	1491 kg
Max. allowed weight	2035 kg

Additional information

· · · · · · · · · · · · · · · · · · ·		
Fuel tank capacity	58	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	.4/14

Number of axles 2

Engine number 7C06588