



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	VERSO VALVEMATIC TREND
Colour	White
Year of manufacture	2014
Top speed	115 mph
Gearbox	7 speed CVT

Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.797 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	41.5 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-09-11
Pictures	3
Listing price	View report



source: heycar.co.uk



MOT history

MOT expiry date	2024-09-30
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	20
Total items failed	8

MOT #11	2023-09-21 14:09
MOT test number	492602105586
Result	✓ Passed
Next expiry date	2024-09-30
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10	2023-09-21 09:14
MOT test number	222901011172
Result	✗ Failed
Fail	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))

MOT #9	2022-09-07 13:04
MOT test number	708502586032
Result	✓ Passed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #8**

2022-09-07 13:04

MOT test number

929645465976

Result**✗ Failed****Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #7**

2021-10-01 09:36

MOT test number

868334021955

Result**✓ Passed****Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #6**

2020-11-20 16:53

MOT test number

897814222627

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #5	2019-05-07 14:43
MOT test number	246385341233
Result	✓ Passed
Advice	Nearside Rear Nail in tyre

MOT #4	2018-05-24 15:38
MOT test number	741829274268
Result	✓ Passed

MOT #3	2017-04-25 12:00
MOT test number	281755884679
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2017-04-07 16:05
MOT test number	405322495093
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #1	2016-10-04 07:55
MOT test number	585504916708
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
30 September 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	30 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	EK64OAD
Plate since	2019-03-28
Current registration	EK64OAD
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-11-03
Last registration	2023-09-21
Complete history	See info



Registration #1	2014-11-03	22 mi
Registration #2	2016-10-04	24.316 mi
Registration #3	2017-04-07	34.065 mi
Registration #4	2017-04-25	34.234 mi
Registration #5	2018-05-24	43.656 mi
Registration #6	2019-05-07	54.676 mi
Registration #7	2020-11-20	73.143 mi
Registration #8	2021-05-20	91.277 mi
Registration #9	2021-05-20	91.277 mi
Registration #10	2021-05-20	91.277 mi
Registration #11	2021-05-20	91.277 mi
Registration #12	2021-05-20	91.277 mi
Registration #13	2021-05-20	91.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4460 mm
Wheel base	2780 mm
Kerb weight	1540 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	2ZRU948349