



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY CC
Colour	Black
Year of manufacture	2011
Top speed	132 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	125 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-10-04
Pictures	58
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-02
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	27
Total items failed	9

MOT #12	2023-11-03 15:57
MOT test number	805750882535
Result	✓ Passed
Next expiry date	2024-11-02

MOT #11	2022-10-17 15:22
MOT test number	746221731616
Result	✓ Passed

Advice O/s rear inner sidelight in/op

**MOT #10**

2022-10-12 14:31

MOT test number

413906939338

Result**✗ Failed****Advice** O/s rear inner sidelight in/op**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (ii))**Fail** Nearside Headlamp light intensity severely reduced no image (4.1.4 (a))**Advice** Tyre light on**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #9**

2021-10-07 10:36

MOT test number

587610196694

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))



MOT #8	2021-01-06 13:57
MOT test number	154802978547
Result	✓ Passed
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7	2019-10-23 11:20
MOT test number	752118485445
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Nearside Front Steering noisy in operation
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

MOT #6	2018-09-08 11:15
MOT test number	368391068200
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #5	2017-09-05 09:33
MOT test number	150055628934
Result	✓ Passed

**MOT #4** 2016-09-08 13:06**MOT test number** 806760521403**Result** ✓ Passed**Advice** Front pads 3-4mm**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-09-08 13:06**MOT test number** 167085778090**Result** ✗ Failed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Front pads 3-4mm**MOT #2** 2015-09-05 09:03**MOT test number** 205633098905**Result** ✓ Passed**MOT #1** 2014-08-22 09:52**MOT test number** 948134734270**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** N/s/r tyre sawtoothed on inside edge**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** O/s/r tyre sawtoothed on inside edge**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
2 November 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	SA61JZH
Plate since	2019-03-29
Current registration	SA61JZH
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-08
Last registration	2023-11-03
Complete history	See info



Registration #1	2011-09-08	18 mi
Registration #2	2014-08-22	55.207 mi
Registration #3	2015-09-05	75.113 mi
Registration #4	2016-09-08	84.917 mi
Registration #5	2016-09-08	84.917 mi
Registration #6	2017-09-05	96.077 mi
Registration #7	2018-09-08	106.010 mi
Registration #8	2019-09-08	116.010 mi
Registration #9	2020-09-08	126.010 mi
Registration #10	2021-09-08	136.010 mi
Registration #11	2022-09-08	146.010 mi
Registration #12	2023-09-08	156.010 mi
Registration #13	2023-11-03	166.010 mi
Registration #14	2023-11-03	176.010 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1417 mm
Length	4799 mm
Wheel base	2708 mm
Kerb weight	1550 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles

2

Engine number

CFF 694226