



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO GBT
Colour	White
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-06-14
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-21
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	56
Total items failed	11

MOT #14	2023-07-19 13:04
MOT test number	105535698057
Result	✓ Passed
Next expiry date	2024-07-21
Advice	Underside of vehicle surface corrosion &treated
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Tyre slightly damaged/cracking or perishing Both fronts (5.2.3 (d) (ii))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #13	2023-07-12 12:44
MOT test number	733002417131
Result	✗ Failed
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Front Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))
Advice	Underside of vehicle surface corrosion &treated
Advice	Tyre slightly damaged/cracking or perishing Both fronts (5.2.3 (d) (ii))
Fail	Headlamp aim too low Both (4.1.2 (a))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2022-07-08 13:52

MOT test number

198937079995

Result

✓ Passed

Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))**Advice** Corrosion to front and rear axles**MOT #11**

2021-07-21 13:24

MOT test number

398308618112

Result

✓ Passed

Advice Second skin on back box loose**Advice** Offside Front Tyre worn close to legal limit/worn on edge Almost worn to cords (5.2.3 (e))**Advice** Oil level on dipstick just above min mark**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil sump corroded and wet**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Minor** Rear fog lamp insecure (4.5.1 (c) (i))

**MOT #10**

2021-07-21 10:54

MOT test number

938566192915

Result**✗ Failed**

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil sump corroded and wet
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Second skin on back box loose
- Minor** Rear fog lamp insecure (4.5.1 (c) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Almost worn to cords (5.2.3 (e))
- Advice** Oil level on dipstick just above min mark
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9

2020-07-22 10:43

MOT test number

203504202255

Result**✓ Passed**

- Advice** Coil spring corroded Both Rear (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Second skin on Back box loose

**MOT #8**

2020-07-21 12:32

MOT test number

968667047847

Result**✗ Failed**

- Advice** Second skin on Back box loose
- Advice** Coil spring corroded Both Rear (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #7

2019-07-13 11:54

MOT test number

812233483190

Result**✓ Passed**

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Oil leak, but not excessive from drive shaft seal (8.4.1 (a) (i))

MOT #6

2019-07-13 08:48

MOT test number

809942797957

Result**✗ Failed**

- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Oil leak, but not excessive from drive shaft seal (8.4.1 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Play in steering rack inner joint(s)

**MOT #5** 2018-07-26 15:11**MOT test number** 734048098467**Result** ✓ Passed**MOT #4** 2017-12-08 14:25**MOT test number** 876372942493**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit nearside and offside (4.1.E.1)**Advice** Exhaust has a minor leak of exhaust gases rear silencer corroded (7.1.2)**MOT #3** 2017-12-06 11:18**MOT test number** 748458648556**Result** ✗ Failed**Advice** Front Tyre worn close to the legal limit nearside and offside (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick nearside and offside (3.5.1g)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Exhaust has a minor leak of exhaust gases rear silencer corroded (7.1.2)**Fail** Front brake disc in such a condition that it is seriously weakened nearside and offside (3.5.1i)**Fail** Offside Rear fog lamp excessively damaged so that it is not visible from a reasonable distance also insecure (1.3.2d)**MOT #2** 2016-12-20 12:55**MOT test number** 849930320084**Result** ✓ Passed**Advice** Exhaust rear silencer corroded**Advice** Offside Rear fog lamp damaged, but still visible from a reasonable distance (1.3.2d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front coil spring worn (2.4.C.1b)



MOT #1	2015-12-05 10:36
MOT test number	795282126460
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
21 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	21 July 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-12-12
Last registration	2023-07-19
Complete history	See info



Registration #1	2012-12-12	24 mi
Registration #2	2015-12-05	17.284 mi
Registration #3	2016-12-20	30.664 mi
Registration #4	2017-12-06	43.951 mi
Registration #5	2017-12-08	43.955 mi
Registration #6	2018-07-26	49.618 mi
Registration #7	2019-07-13	53.047 mi
Registration #8	2019-07-13	53.047 mi
Registration #9	2019-07-13	53.047 mi
Registration #10	2019-07-13	53.047 mi
Registration #11	2019-07-13	53.047 mi
Registration #12	2019-07-13	53.047 mi
Registration #13	2019-07-13	53.047 mi
Registration #14	2019-07-13	53.047 mi
Registration #15	2019-07-13	53.047 mi
Registration #16	2019-07-13	53.047 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2

Engine number	0091898
---------------	---------