



Mercedes-Benz




report date: 2024-10-11

General information

| | |
|---------------------|------------------|
| Make | MERCEDES-BENZ |
| Model | VITO 114 PURE L2 |
| Colour | White |
| Year of manufacture | 2019 |
| Top speed | 121 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 100 kW / 136 HP / 136 BHP |
| Max. torque | 330 Nm at 2.400 rpm |
| Engine capacity | 2.143 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 33.6 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 43.5 mpg |
| CO2 emission | 179 g/km |
| CO2 label | I |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-11-07 |
| MOT pass rate | 60 % |
| MOT passed | 3 |
| Failed MOT tests | 2 |
| Total advice items | 3 |
| Total items failed | 8 |

| | |
|------------------|------------------|
| MOT #5 | 2024-10-22 11:12 |
| MOT test number | 588980655521 |
| Result | ✓ Passed |
| Next expiry date | 2025-11-07 |

| | |
|-----------------|------------------|
| MOT #4 | 2023-11-01 15:33 |
| MOT test number | 292612616568 |
| Result | ✓ Passed |

| | |
|-----------------|---|
| MOT #3 | 2023-11-01 10:22 |
| MOT test number | 282995782622 |
| Result | ✗ Failed |
| Fail | Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) |

| | |
|-----------------|--|
| MOT #2 | 2022-11-08 12:43 |
| MOT test number | 491422638610 |
| Result | ✓ Passed |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii)) |
| Advice | Engine cover fitted |



MOT #1 2022-10-21 09:13

MOT test number 938952999184

Result ✗ Failed

- Fail** Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
7 November 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 173 |
| MOT expiry date | 7 November 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|----------------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|------------------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|-------|-----|
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | BD69ZHY |
| Plate since | 2019-09-29 |
| Current registration | BD69ZHY |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company

REDACTED

Date of agreement

REDACTED

Agreement type

REDACTED

Agreement term

REDACTED

Agreement number

REDACTED

Contact info

REDACTED

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 6 |
| First mileage registration | 2019-10-31 |
| Last registration | 2024-10-22 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2019-10-31 | 18 mi |
| Registration #2 | 2022-10-21 | 89.927 mi |
| Registration #3 | 2022-11-08 | 90.258 mi |
| Registration #4 | 2023-10-22 | 91.277 mi |
| Registration #5 | 2023-10-22 | 91.277 mi |
| Registration #6 | 2024-10-22 | 91.277 mi |

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2249 mm |
| Height | 1910 mm |
| Length | 5140 mm |
| Wheel base | 3200 mm |
| Kerb weight | 2056 kg |
| Max. allowed weight | 2800 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 57 l |
| Fuel delivery | Direct Injection |
| Number of seats | 3 |

| | |
|------------------------|----------------|
| Number of axles | 2 |
| Engine number | 65195035142045 |