





report date: 2024-03-28

General information

| Make | FORD |
|---------------------|---------------------|
| Model | TRANSIT 350 H/R P/V |
| Colour | White |
| Year of manufacture | 2009 |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 113 BHP |
|-----------------|----------|
| Engine capacity | 2.402 cc |
| Cylinders | 4 |
| Fuel type | Diesel |



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-08

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-11-22 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 12 |
| Failed MOT tests | 6 |
| Total advice items | 30 |
| Total items failed | 14 |

| MOT #18 | 2023-11-23 14:09 |
|--|------------------|
| MOT test number | 315612084231 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-22 |
| Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) | |

| MOT #17 2023 | 3-11-23 08:44 |
|--|-----------------|
| MOT test number 55 | 20375405908 |
| Result | X Failed |
| Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) | |

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #16 2023-11-13 09:17 446537060944 **MOT** test number Result × Failed Fail Offside Rear Leaf spring fractured (5.3.1 (b) (i)) **Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Fail Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i)) Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #15

MOT test number

829715647414

Result

✓ Passed

MOT #14 2021-12-31 11:53

MOT test number 592186922158

Result ✓ Passed

Advice N/s/f tyre worn low on outer edge

Advice Front discs worn/corroded

Advice Rear brake pads low

Advice Slight play in n/s/f steering arm

Advice Front brake pads low

CarCheck.co.uk page 4/15



Fail

AD59YRW

report date: 2024-03-28

MOT #13 2021-12-30 13:35 **MOT** test number 266383190143 Result × Failed **Advice** Front brake pads low Fail Offside Front Tyre tread depth below requirements of 1.6mm 215/75 r16 (5.2.3 (e)) **Advice** N/s/f tyre worn low on outer edge Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i)) Fail Advice Front discs worn/corroded Rear brake pads low Advice **Advice** Slight play in n/s/f steering arm

MOT #12 2020-12-09 09:45

MOT test number 481667053918

Result ✓ Passed

Central Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #11 2020-12-03 09:28 186669837581 **MOT** test number Result × Failed Fail Offside Front Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Fail Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i)) **Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))Advice Central Front Anti-roll bar pin or bush worn but not resulting in excessive movement Dee bushes have slight play (5.3.4 (a) (i))

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #10 2019-12-02 10:34

MOT test number 567492819216

Result
✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Front Suspension component pin or bush slightly worn Both Dee bushes on anti roll bar. (5.3.4 (a) (i))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #9 2019-12-02 10:34

MOT test number 700883298102

Result X Failed

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Front Suspension component pin or bush slightly worn Both Dee bushes on anti roll bar. (5.3.4 (a)

MOT #8 2018-12-07 09:51

MOT test number 949751325649

Result

Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

CarCheck.co.uk page 6/15



report date: 2024-03-28

× Failed

MOT #7 2018-11-30 09:12

MOT test number 863595311469

Result

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Fail Offside Rear Brake disc contaminated hub seal leaking (1.1.14 (b))

Fail Offside Rear Brake pad(s) contaminated (1.1.13 (b))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

MOT #6 2017-12-08 09:42

MOT test number 450308231767

Result \rightarrow Passed

Advice Nearside Rear hub seal slightly damp

MOT #5 2016-12-07 09:47

MOT test number 774288490821

Result ✓ Passed

MOT #4 2015-11-30 09:22

MOT test number 471515028522

Result

✓ Passed

Advice Nearside Front wheel bearing has slight play (2.5.A.3c)

MOT #3 2014-12-05 09:31

MOT test number 335339134321

Result
✓ Passed

MOT #2 2013-12-09 09:40

MOT test number 655143243362

Result
✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #1 2012-12-03 09:56

MOT test number 488838532407

Result ✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-28

Tax & MOT check



Days left 94

MOT expiry date 22 November 2024

Full MOT history See MOT history

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

| _ | |
|--------|-----------|
| Owner | history |
| OWITCE | ilistoi y |

| , | | |
|---|-------------|--|
| For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report | | |
| ********* | | |
| *************************************** | | |
| *********** | | |
| | | |
| ********* | | |
| | | |
| *************************************** | | |
| | More info > | |
| Plate changes | | |
| See in this check if this FORD had different number plates. | | |
| Number of plates | | |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info > | |

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 20 |
| First mileage registration | 2009-12-29 |
| Last registration | 2023-11-23 |
| Complete history | See info |



| Registration #1 | 2009-12-29 | 25 mi |
|------------------|------------|------------|
| Registration #2 | 2012-12-03 | 31.617 mi |
| Registration #3 | 2013-12-09 | 44.615 mi |
| Registration #4 | 2014-12-05 | 61.939 mi |
| Registration #5 | 2015-11-30 | 73.143 mi |
| Registration #6 | 2016-12-07 | 85.411 mi |
| Registration #7 | 2017-12-08 | 96.813 mi |
| Registration #8 | 2018-11-30 | 107.041 mi |
| Registration #9 | 2018-12-07 | 107.228 mi |
| Registration #10 | 2019-12-02 | 118.119 mi |
| Registration #11 | | 71.777 es |
| Registration #12 | | 77.777 44 |
| Registration #13 | | 11.177 es |
| Registration #14 | | 71.777 es |
| Registration #15 | | 11.177 es |
| Registration #16 | | 11.177 es |
| Registration #17 | | 11.177 es |
| Registration #18 | | 11.177 es |
| Registration #19 | | 11.177 es |
| Registration #20 | | 11.177 es |
| | | |

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-28

Car features

| 50225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Dimensions & weight

| Width | 2374 mm |
|---------------------|---------|
| Height | 2543 mm |
| Length | 5680 mm |
| Kerb weight | 2062 kg |
| Max. allowed weight | 3500 kg |

Additional information

| Fuel tank capacity | 80 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 3 |
| Engine number | 8K44781 |

CarCheck.co.uk page 15/15