



report date: 2024-03-29

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS EGS PICASSO
Colour	Brown
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-09-15
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-04-05
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	17
Total items failed	12

MOT #15	2024-03-06 11:41
MOT test number	247528101949
Result	✓ Passed
Next expiry date	2025-04-05
Advice	Brake disc worn, but not excessively Fronts and rears (1.1.14 (a) (i))

MOT #14	2024-03-06 11:41
MOT test number	985188241811
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Brake disc worn, but not excessively Fronts and rears (1.1.14 (a) (i))
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #13	2023-03-31 12:17
MOT test number	784534564747
Result	✓ Passed

**MOT #12**

2023-03-31 08:32

**MOT test number**

156831566861

**Result****✗ Failed****Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.4mm (5.2.3 (e))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #11**

2022-03-30 08:40

**MOT test number**

668004036001

**Result****✓ Passed****MOT #10**

2021-04-06 14:41

**MOT test number**

812846276961

**Result****✓ Passed****Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9**

2021-04-06 12:42

**MOT test number**

677598016799

**Result****✗ Failed****Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8** 2019-07-31 14:16**MOT test number** 302359606259**Result** ✓ Passed**MOT #7** 2018-07-20 09:49**MOT test number** 369014080126**Result** ✓ Passed**MOT #6** 2017-06-16 10:23**MOT test number** 578466133847**Result** ✓ Passed**MOT #5** 2016-06-16 15:02**MOT test number** 494541803039**Result** ✓ Passed**Advice** Engine covers fitted obscuring view of engine bay components**Advice** Under trays fitted obscuring view of underside components**MOT #4** 2015-07-13 15:01**MOT test number** 248994195117**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Front discs corroded

**MOT #3** 2014-07-10 11:19**MOT test number** 927301594127**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** All discs lipped**Notice** Under-trays fitted obscuring some underside components**Notice** Turbo hose loose**Notice** Front tyres wearing on edges**MOT #2** 2013-07-05 16:44**MOT test number** 276316883402**Result** ✓ Passed**MOT #1** 2013-07-04 16:51**MOT test number** 737555583196**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
5 April 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	5 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-06-29
Current registration	 XXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-15
Last registration	2024-03-06
Complete history	<a href="#">See info</a>



Registration #1	2010-07-15	9 mi
Registration #2	2013-07-04	40.029 mi
Registration #3	2013-07-05	40.030 mi
Registration #4	2014-07-10	50.019 mi
Registration #5	2015-07-13	61.022 mi
Registration #6	2016-06-16	69.010 mi
Registration #7	2017-06-16	80.288 mi
Registration #8	2018-07-20	90.664 mi
Registration #9	2019-07-31	92.987 mi
Registration #10	2020-06-20	95.377 mi
Registration #11	2021-06-20	95.377 mi
Registration #12	2022-06-20	95.377 mi
Registration #13	2023-06-20	95.377 mi
Registration #14	2024-03-06	95.377 mi
Registration #15	2024-03-06	95.377 mi
Registration #16	2024-03-06	95.377 mi
Registration #17	2024-03-06	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1830 mm
Height	1680 mm
Length	4470 mm
Wheel base	2728 mm
Kerb weight	1499 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBBN0277393