





report date: 2024-03-29

General information

Make	MINI
Model	CLUBMAN JOHN COOPER WORKS
Colour	Grey
Year of manufacture	2016
Top speed	153 mph
0 - 60 mph	6.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	228 BHP
Max. torque	320 Nm at 1.250 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/11



Internet history

Entr	. 1
EIIU	vт

Life y 1	
Date	2021-06-07
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-07-07
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #7	2023-07-08 10:27
MOT test number	257589553551
Result	✓ Passed
Next expiry date	2024-07-07

MOT #6		2023-07-08 08:17
MOT test	number	161047955743
Result		X Failed
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened badly corroded on inside faces nearside and offside (1.1.14 (a) (ii))		
Advice Tyre pressure warning lamp on		
Fail 0	ffside Front Service brake excessively fluctuating (1.2.1 (e))	

MOT #5	2022-06-14 14:00
MOT test	number 773964407007
Result	✓ Passed
Advice Front Service brake fluctuating, but not excessively nearside and offside (1.2.1 (e))	
Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/11



MOT #4 2022-06-14 11:54

MOT test number 679327912435

Result X Failed

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Service brake fluctuating, but not excessively nearside and offside (1.2.1 (e))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #3 2021-06-29 16:09

MOT test number 139524375535

Result
✓ Passed

MOT #2 2020-09-05 09:49

MOT test number 847898595803

MOT #1 2019-08-27 09:12

MOT test number 207789219016

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	7 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report h		e?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK CONTRACTOR	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-09-07
Last registration	2023-07-08
Complete history	See info



Registration #1	2016-09-07	11 mi
Registration #2	2019-08-27	32.244 mi
Registration #3	2020-09-05	40.667 mi
Registration #4		11.777 es
Registration #5	2021-06-29	47.769 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		70,707 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3874 mm
Wheel base	1932 mm
Kerb weight	1280 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	44	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	4	page 11/11

Number of axles 2

Engine number F392H243