



LMI7POV

report date: 2024-03-28

General information

Make	BMW
Model	216 216D SPORT GRAN TOURER
Colour	Silver
Year of manufacture	2017
Top speed	119 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.496 cc
Cylinders	3
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	B





Internet history

Entry 2

Date	2021-07-24
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-07-23
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-15
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #7	2023-08-08 14:58
MOT test number	462359623370
Result	✓ Passed
Next expiry date	2024-08-15
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2023-08-08 14:58
MOT test number	688399746633
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))

**MOT #5**

2022-08-11 14:12

MOT test number

545069802218

Result

✓ Passed

Advice Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall. (5.2.3 (d) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall. O/S & N/S (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened O/S & N/S (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement O/S & N/S (5.3.4 (a) (i))

MOT #4

2022-08-11 14:12

MOT test number

885239241587

Result

✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened O/S & N/S (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement O/S & N/S (5.3.4 (a) (i))

Advice Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall. (5.2.3 (d) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Nearside Front Headlamp aim too high (4.1.2 (a))

Advice Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall. O/S & N/S (5.2.3 (d) (i))

MOT #3

2021-08-16 13:17

MOT test number

885637839519

Result

✓ Passed



MOT #2	2020-11-17 12:45
MOT test number	642446153166
Result	✓ Passed

MOT #1	2020-05-11 09:46
MOT test number	490302393922
Result	✓ Passed

Advice COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
15 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-05-19
Last registration	2023-08-08
Complete history	See info



Registration #1	2017-05-19	16 mi
Registration #2	2020-11-17	40.598 mi
Registration #3	2020-05-20	35.277 mi
Registration #4	2020-05-20	35.277 mi
Registration #5	2021-08-16	44.538 mi
Registration #6	2020-05-20	35.277 mi
Registration #7	2020-05-20	35.277 mi
Registration #8	2020-05-20	35.277 mi
Registration #9	2020-05-20	35.277 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1800 mm
Height	1612 mm
Length	4556 mm
Wheel base	2780 mm
Kerb weight	1470 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	30899958