



J399MJK

report date: 2024-03-29

General information

Make	NISSAN
Model	FIGARO
Colour	Green
Year of manufacture	1991
Gearbox	-

Engine & fuel consumption

Engine capacity	980 cc
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 2

Date	2022-02-10
Pictures	11
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2022-01-21
Pictures	11
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-18
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	24
Total items failed	22

MOT #23 2024-04-19 17:18

MOT test number 544358020432

Result ✓ Passed

Next expiry date 2025-04-18

Advice Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #22 2023-04-13 13:33

MOT test number 456236504056

Result ✓ Passed

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #21 2022-01-10 12:50

MOT test number 172304132489

Result ✓ Passed

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #20** 2021-01-12 16:48**MOT test number** 854083065986**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #19** 2019-07-04 09:20**MOT test number** 420262939320**Result** ✓ Passed**Advice** Gearbox mounting defective**Advice** Under vehicle has slight corrosion**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #18** 2018-08-06 12:54**MOT test number** 546964096801**Result** ✓ Passed**Advice** Gearbox mounting defective**Advice** Rear Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))**Advice** Lower Integral body structure is corroded but structural rigidity is not significantly reduced both sides (6.1.1 (c) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #17** 2017-08-12 16:06**MOT test number** 833341323323**Result** ✓ Passed**MOT #16** 2015-12-18 15:56**MOT test number** 354347958437**Result** ✓ Passed

**MOT #15** 2015-01-05 12:59**MOT test number** 715925505085**Result** ✓ Passed**MOT #14** 2014-01-16 14:14**MOT test number** 385826814027**Result** ✓ Passed**MOT #13** 2013-07-22 12:28**MOT test number** 168513303244**Result** ✗ Failed**Advice** Nearside Front Headlamp damaged but light output not reduced (1.7.5a)**Fail** Offside Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Offside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Battery insecure (1.9.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Windscreen wiper not operating over a large enough area to give an adequate view (8.2.1c)**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Fail** Nearside Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Nearside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Fail** Power steering component(s) leaking (2.3.3b)

**MOT #12** 2012-08-09 17:01**MOT test number** 816782122212**Result** ✓ Passed**MOT #11** 2012-08-09 10:53**MOT test number** 319712022225**Result** ✗ Failed**Fail** Power steering component(s) leaking (2.3.3b)**MOT #10** 2010-11-27 16:29**MOT test number** 914821030374**Result** ✓ Passed**MOT #9** 2010-11-26 13:45**MOT test number** 460770630337**Result** ✗ Failed**Fail** Rear fog lamp switch missing (1.3.1a)**Fail** Offside Front constant velocity joint gaiter split (2.5.C.1a)**Fail** Rear fog lamp missing (1.3.2a)**MOT #8** 2009-11-10 17:01**MOT test number** 400324719440**Result** ✓ Passed

**MOT #7** 2009-11-09 10:05**MOT test number** 680913919301**Result** ✗ Failed**Advice** Power steering pump has slight seepage from a seal (2.3.3b)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Notice** N/s/r tyre are perished**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #6** 2008-10-29 11:40**MOT test number** 333213108370**Result** ✗ Failed**Pass with rectification** Rear fog lamp switch missing (1.3.1a)**MOT #5** 2008-10-29 11:40**MOT test number** 910373608344**Result** ✓ Passed**MOT #4** 2007-11-21 12:55**MOT test number** 823085827359**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2006-09-15 16:16**MOT test number** 663128456249**Result** ✓ Passed



MOT #2	2006-09-14 15:10
MOT test number	110017556239
Result	✗ Failed
Fail	Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)
Fail	Offside Inner Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Brakes imbalanced across an axle (3.7.B.5b)
Fail	Parking brake lever has no reserve travel (3.1.6b)

MOT #1	2005-09-01 11:08
MOT test number	703674645244
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
18 April 2025

Tax status

Valid until 1 April

Days left

336

MOT expiry date

18 April 2025

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	25
First mileage registration	1991-01-01
Last registration	2024-04-19
Complete history	See info



Registration #1	1991-01-01	20 mi
Registration #2	2005-09-01	51.349 mi
Registration #3	2006-09-14	88.715 mi
Registration #4	2006-09-15	55.137 mi
Registration #5	2007-11-21	57.260 mi
Registration #6	2008-10-29	96.795 mi
Registration #7	2009-11-09	100.241 mi
Registration #8	2009-11-10	100.241 mi
Registration #9	2010-11-26	102.227 mi
Registration #10	2010-11-27	102.227 mi
Registration #11	2012-08-09	64.735 mi
Registration #12	2012-08-09	104.158 mi
Registration #13	2013-07-22	104.937 mi
Registration #14	2013-07-22	104.937 mi
Registration #15	2013-07-22	104.937 mi
Registration #16	2013-07-22	104.937 mi
Registration #17	2013-07-22	104.937 mi
Registration #18	2013-07-22	104.937 mi
Registration #19	2013-07-22	104.937 mi
Registration #20	2013-07-22	104.937 mi
Registration #21	2013-07-22	104.937 mi
Registration #22	2013-07-22	104.937 mi
Registration #23	2013-07-22	104.937 mi
Registration #24	2013-07-22	104.937 mi
Registration #25	2013-07-22	104.937 mi



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Number of seats

4

Engine number

NOT KNOWN