



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX GHIA TDCI
Colour	Black
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G





## Internet history

### Entry 1

Date	2021-02-27
Pictures	5
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2024-11-15
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	66
Total items failed	2

MOT #16	2023-11-02 10:25
MOT test number	489084236358
Result	✓ Passed
Next expiry date	2024-11-15
Advice	Offside Front mirror casing insecure
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Coil spring corroded both side (5.3.1 (b) (i))

MOT #15	2022-11-09 13:46
MOT test number	884468585420
Result	✓ Passed
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Offside Front mirror casing insecure
Minor	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2021-11-15 15:57

**MOT test number**

930406047009

**Result**

✓ Passed

**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13**

2021-11-12 12:22

**MOT test number**

931184812582

**Result**

✗ Failed

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Central Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2020-11-06 14:04

**MOT test number**

789883705401

**Result**

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Coolant level low
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil level on minimum

**MOT #11**

2019-11-08 09:03

**MOT test number**

536022913124

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2019-11-08 09:03

**MOT test number**

677765307211

**Result**

✗ Failed

- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2018-11-09 14:11**MOT test number** 303255022974**Result** ✓ Passed

- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Inflation kit out of date
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8** 2018-11-09 13:22**MOT test number** 282880205935**Result** ✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Inflation kit out of date
- MAJOR** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #7** 2017-11-10 16:34**MOT test number** 925331430336**Result** ✓ Passed**Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Offside engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)**MOT #6** 2017-11-10 16:34**MOT test number** 608225484623**Result** ✗ Failed**Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)**MOT #5** 2016-11-04 12:09**MOT test number** 819850491627**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Tyre sealant expired**MOT #4** 2015-11-13 12:53**MOT test number** 900311238728**Result** ✓ Passed**Advice** Child seat fitted os rear**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2014-11-11 09:31**MOT test number** 798875514325**Result** ✓ Passed

- Notice** Nearside rear tyre valve stem perished
- Advice** Nearside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)
- Notice** Front brake pads wearing low
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)
- Notice** Offside rear tyre valve stem perished
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #2** 2013-11-12 09:01**MOT test number** 406436913394**Result** ✓ Passed**MOT #1** 2012-11-16 09:59**MOT test number** 405841222350**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
15 November 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	368
<b>MOT expiry date</b>	15 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	HN59FKX
Plate since	2019-03-28
Current registration	HN59FKX
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-10-30
Last registration	2023-11-02
Complete history	<a href="#">See info</a>



Registration #1	2009-10-30	10 mi
Registration #2	2012-11-16	48.214 mi
Registration #3	2013-11-12	60.168 mi
Registration #4	2014-11-11	74.332 mi
Registration #5	2015-11-13	87.863 mi
Registration #6	2016-11-04	97.597 mi
Registration #7	2017-11-10	106.947 mi
Registration #8	2017-11-10	106.947 mi
Registration #9	2018-11-09	116.728 mi
Registration #10	2019-11-09	126.509 mi
Registration #11	2020-11-09	136.290 mi
Registration #12	2021-11-09	146.071 mi
Registration #13	2022-11-09	155.852 mi
Registration #14	2023-11-02	165.633 mi
Registration #15	2023-11-02	175.414 mi
Registration #16	2023-11-02	185.195 mi
Registration #17	2023-11-02	194.976 mi
Registration #18	2023-11-02	204.757 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	9K79192