



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D DRIVE SE
Colour	White
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 2

Date	2021-06-25
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-09
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-10
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	22
Total items failed	6

MOT #12 2023-06-03 12:53

MOT test number 783108106985

Result ✓ Passed

Next expiry date 2024-06-10

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #11 2022-06-11 09:57

MOT test number 759425406738

Result ✓ Passed

MOT #10 2022-05-19 13:32

MOT test number 272514725375

Result ✗ Failed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Nail in tyre

**MOT #9** 2021-05-04 15:06**MOT test number** 344381876149**Result** ✓ Passed**MOT #8** 2019-06-05 11:49**MOT test number** 655338301336**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge side wall slightly damaged (5.2.3 (e))**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-06-03 11:09**MOT test number** 543120748938**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge side wall slightly damaged (5.2.3 (e))**MOT #6** 2018-05-01 11:58**MOT test number** 519600896060**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Under tray fitted unable to see some testable items

**MOT #5** 2018-04-30 08:09**MOT test number** 174562674011**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Under tray fitted unable to see some testable items**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #4** 2017-04-18 14:08**MOT test number** 136716527497**Result** ✓ Passed**MOT #3** 2016-03-03 14:39**MOT test number** 776784459630**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2016-03-03 11:06**MOT test number** 425043715050**Result** ✗ Failed**Fail** Offside Headlamp cleaning device inoperative (1.7.2)**Fail** Nearside Headlamp cleaning device inoperative (1.7.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2015-02-02 12:12**MOT test number** 407623335072**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
10 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	10 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	ND61YVF
Plate since	2019-09-29
Current registration	ND61YVF
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-02-10
Last registration	2023-06-03
Complete history	See info



Registration #1	2012-02-10	8 mi
Registration #2	2015-02-02	56.873 mi
Registration #3	2016-03-03	66.266 mi
Registration #4	2016-03-03	66.266 mi
Registration #5	2017-04-18	73.887 mi
Registration #6	2018-04-30	82.808 mi
Registration #7	2018-05-01	82.808 mi
Registration #8	2019-06-03	89.245 mi
Registration #9	2020-06-03	95,377 miles
Registration #10	2021-06-03	95,377 miles
Registration #11	2022-06-03	95,377 miles
Registration #12	2023-06-03	95,377 miles
Registration #13	2024-06-03	95,377 miles
Registration #14	2025-06-03	95,377 miles
Registration #15	2026-06-03	95,377 miles

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2041867