





report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Silver
Year of manufacture	2008
Top speed	125 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	1.988 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-06

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2022-06-22
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	30
Total items failed	12

MOT #15	2021-06-07 13:33	
MOT test number	208484925404	
Result	✓ Passed	
Next expiry date	2022-06-22	
Advice Nearside Rear Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))		
Advice Brake hose has slight corrosion to ferrule all (1.1.12 (f) (i))		
Advice Suspension components corroded / all 4 coil springs corroded		

 MOT #14
 2021-05-28 14:43

 MOT test number
 988044294754

 Result
 X Failed

Advice Nearside Rear Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))

Advice Suspension components corroded / all 4 coil springs corroded

Fail Offside Rear Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced outer sill (6.1.1 (c) (i))

Advice Brake hose has slight corrosion to ferrule all (1.1.12 (f) (i))

MOT #13	2020-06-23 08:45
MOT test number	688183978541
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12		2019-04-29 09:50
MOT test	number	680658771970
Result		✓ Passed
MOT #11		2018-05-01 11:25
MOT test	number	955627734305
Result		✓ Passed
Advice	OSF tyre worn	
Advice	Both rear coil springs corroded	
Advice	Engine very noisy around ribbed belt area	
Advice	Oil leak	
Advice	Both rear tyres perished	

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #10 2018-04-27 12:45 470944929945 **MOT** test number Result × Failed **Advice** Front Brake pad(s) wearing thin (3.5.1g) **Advice** OSF tyre worn Fail Front Brakes imbalanced across an axle (3.7.B.5b) Advice Both rear coil springs corroded Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b) Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Engine very noisy around ribbed belt area Fail Offside Front Valve stem seriously damaged (4.1.D.1e) Advice Both rear tyres perished Fail Headlamp aim too low Both (1.8) **Advice** Oil leak

MOT #9	2017-04-27 09:26
MOT test number	227030867030
Result	✓ Passed
MOT #8	2016-04-06 15:30
MOT test number	412021652854
Result	✓ Passed

CarCheck.co.uk page 5/13



(2.4.G.2)

AB08DMU

report date: 2024-03-28

2016-04-05 14:45 **MOT #7 MOT** test number 517844591774 Result × Failed Fail Offside Front Wheel nut(s) loose (4.2.A.1e) Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a) **Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)Fail Nearside Front Wheel nut(s) loose (4.2.A.1e) Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Fail (4.1.D.1a) Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement **Advice**

MOT #6	2015-04-29 13:38
MOT test number	777639615133
Result	✓ Passed
MOT #5	2015-04-28 09:50
MOT test number	175298815129
Result	X Failed
Fail Rear Brake lining(s) less than 1.5 mm thick (3.5.1g)	
Fail Offside Rear Shock absorber has a serious fluid leak (2.7.3)	
Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3)	

MOT #4		2014-04-16 09:51
MOT test	number	545996804105
Result		✓ Passed
Notice Advice	Engine covers fitted obscuring some components in the engine bay Offside Rear coil spring corroded (2.4.C.1b)	
Advice	Nearside Rear coil spring corroded (2.4.C.1b)	

CarCheck.co.uk page 6/13



report date: 2024-03-28

MOT #3 2013-04-16 15:03 MOT test number 539896303187

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2012-04-17 10:16

MOT test number 956778402154

Result

Passed

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1 2011-07-20 09:29

MOT test number 309471901240

Result
✓ Passed

Advice Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner	history
OWITE	THISCOLY

*		
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full r		AR

THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-06-26
Last registration	2021-06-07
Complete history	See info



Registration #1	2008-06-26	18 mi
Registration #2	2011-07-20	46.867 mi
Registration #3	2012-04-17	49.991 mi
Registration #4	2013-04-16	60.767 mi
Registration #5	2014-04-16	71.957 mi
Registration #6	2015-04-28	83.304 mi
Registration #7	2015-04-29	83.324 mi
Registration #8	2016-04-05	90.984 mi
Registration #9	2016-04-06	90.996 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		
Registration #16		11.777 46

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0806030302416G

CarCheck.co.uk page 13/13